

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON Wells, NM 88240

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Novy Oil & Gas, Inc.

3. Address and Telephone No.

125 N. MARKET ST., SUITE 1230, WICHITA, KS 67202 (316) 265-4651

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 1980' FWL SEC. 5 - T9S - R34E

5. Lease Designation and Serial No.
NMNM0202771

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Sunoco #1

9. API Well No.
30-025-23689

10. Field and Pool, or Exploratory Area
VADA PENN

11. County or Parish, State
Lea County, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☐ Subsequent Report

☒ Final Abandonment Notice

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)*

- MIRU - POOH WITH RODS.
 - POOH WITH TUBING. RUN GUAGE RING TO 1641, POOH, PUMP 20 BBLS FRESH WTR
 - RIH WITH GUAGE RING TO 6240, RIH WITH TBG AND SPOT 26 SX PLUG AT 9500' POOH.
 - RIH WITH TBG AND TAG CEMENT AT 9300' POOH RIH W/ CIBP & SET @ 8675 RIH & CIRC 10# MUD
 - PUMP 120 BBL MUD ON VAC. SPOT 15 SX PLUG @ 8675 - 8550 POOH & SPOT 25 SX @ 7899. POOH.
 - RIH NO TAG POOH RIH W/ CIBP AND SET @ 7900. RIH CIR 10# SPOT 15 SX ON TOP POOH
 - RIG UP CSG JACKS. CSG FREE AT 3400 CUT @ 4150 PER BLM RIH WITH PKR AND PRESSURE TO 1000 # POOH. RIH OPEN ENDED TO 4260 POOH TO 3500 SPOT 25 SX. POOH
 - RIH W/ TBG PER BLM TAG POOH RIH & CUT CSG @ 3424 POOH W/ CSG. RIH SPOT 45SX @ 3483
 - RIH TAG @ 3277 POOH & PERF @ 1996 TEST TO 1100# UNDER 8 5/8 PKR @ 1500 PER BLM POOH RIH SPOT 45 SX @ 2052 POOH
 - RIH & TAG @ 1919 POOH
 - RIH CUT CGS @ 475 LAY DOWN. RIH SPOT 80 SX @ 528 POOH WOC RIH NO TAG SPOT 80 SX @ 528 POOH
 - RIH TAG @ 378 SPOT 20 SX @ 378 - 338 TAGGED POOH RIG DN CUT OFF WELLHEAD & ANCHORS SPOT 20 SX @ 60' TO SURFACE
- INSTALL DRY HOLE MARKER MOVE OUT.

APPROVED

JUL 10 2002

GARY GOURLEY
PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Signed

(This space for Federal or State office use)

Title VICE PRESIDENT

Date

7/1/02

Approved by

Conditions of approval, if any:

Title

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

MAYO MARRS CASING PULLING INC.

NOVY OIL & GAS

Lease: SUNOCO # 1

Project: P & A

5-20-02

NOTIFY BLM - MOVE IN RIG UP - DIG & LINE WORKING PIT - POOH WITH 63-1" RODS & 108-7/8" RODS - SHUT DOWN
(6 HRS RIG)

5-21-02

POOH WITH TOTAL OF 384 RODS - NUBOP & FLANGE - POOH WITH TUBING 138 STANDS - RIH WITH GAUGE RING TO 1641' - WOULD NOT GO - POOH - PUMP 20 BBLS FRESH WATER
CLOSE IN WELL
(11 HRS)

5-22-02

RIH WITH GAUGE RING TO 6240' - CALL BLM - THEY ADD PLUG @ 9500' - RIH WITH TUBING & SPOT 26 SXS @ 9500' - POOH - CLOSE IN WELL
(10 HRS)

5-23-02

RIH & TAG @ 9300' - POOH - RIH WITH CIBP & SET @ 8675' - RIH WITH TUBING & CIR. 10# MUD - 62 SXS SALT CLAY - CLOSE IN WELL
(12 HRS)

5-24-02

PUMP 120 BBLS MUD - WELL ON VACUUM - CALL BLM - TALK THEM INTO LETTING US SPOT PLUGS - THEY WANTED TO LOCATE HOLES IN CASING - SPOT 15 SXS @ 8675'-8580' - POOH & SPOT 25 SXS @ 7899' - POOH - CLOSE IN WELL - WILL TAG PER BLM TUESDAY
(8 HRS)

5-28-02

RIH - NO TAG - POOH WITH TUBING - RIH & SET CIBP @ 7900' - RIH - CIR. 10# MUD - SPOT 15 SXS ON TOP - POOH - CLOSE IN WELL
(11 HRS)

5-29-02

FINISH POOH WITH TUBING - WELD ON 5 1/2" PULL NIPPLE - RIG UP CASING JACKS - FREEPOINT CASING @ 3400' - RIH & CUT @ 4150' PER BLM - PRESSURE TEST CASING WITH PACKER TO 1000# FOR 15 MINUTES - POOH - RIH OPEN-ENDED TO 4260' - SPOT 25 SXS - POOH TO 3500'
(12 HRS)

5-30-02

RIH & TAG WITH TUBING PER BLM @ 3995' - POOH - RIH & CUT CASING @ 3424' - LAY DOWN CASING - RIH & SPOT 45 SXS @ 3483' - POOH
(12 HRS)

5-31-02

RIH & TAG @ 3277' - POOH - RIH & PERFORATE @ 1996' - TEST TO 1100# UNDER 8 5/8"
PACKER @ 1500' PER BLM - POOH - RIH & SPOT 45 SXS @ 2052' - POOH - WOC - RIH & TAG
@ 1919' - POOH - WELD ON 8 5/8" CASING PULL NIPPLE
(11 HRS)

6-03-02

RIH & CUT CASING @ 475' - LAY DOWN CASING - RIH & SPOT 80 SXS @ 528' - POOH - WOC
RIH & NO TAG - SPOT 80 SXS @ 528' - POOH - CLOSE IN WELL
(12 HRS)

6-04-02

RIH & TAG CEMENT WITH TUBING @ 378' - SPOT 20 SXS @ 378' - 338' - TAGGED - POOH -
RIG DOWN - CUT OFF WELLHEAD AND ANCHORS - SPOT 20 SXS @ 60' TO SURFACE -
INSTALL DRY HOLE MARKER - MOVE OUT
(8 HRS)

MAYO MARRS CASING PULLING INC.
BOX 863
HERMIT, TEXAS 79745

NOVY OIL & GAS, INC.

Lease: SUNOCO # 1

Project: P & A – CEMENTING REPORT

05-22-2002 - SPOT 26 SXS @ 9500'-9300' TAGGED
05-23-2002 - SET CIBP @ 8,675' - SPOT 15 SXS ON TOP - 8580'
05-24-2002 - SPOT 25 SXS @ 7899' - NO TAG
05-28-2002 - SET CIBP @ 7900' - SPOT 15 SXS ON TOP - 7762'
05-29-2002 - PERFORATE @ 4150' COULD NOT PUMP INTO PERFS
05-29-2002 - SPOT 25 SXS @ 4260'-3995' TAGGED
05-30-2002 - SPOT 45 SXS @ 3483'-3277' TAGGED
05-31-2002 - PERFORATE @ 1996' COULD NOT PUMP INTO PERFS
05-31-2002 - SPOT 45 SXS @ 2052'-1919' TAGGED
06-03-2002 - SPOT 180 SXS @ 528' - 338' TAGGED
06-04-2002 - SPOT 20 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER
CIRCULATE 10# MUD