NEW MEXICO OIL CONSERVATION COMMISSION F. O. BOX 1980 HOBBS, NEW MEXICO 88240

DATE March 3, 1972
And Drilling 30.
Eox 1030
Midland, Texas 79701
Re: Plugging Reports
Gentlemen:
Form C-103, Report of Plugging, for your Hudson State #1-P 1-10-32
Lease Well No. Unit S-T-cannot be approved until a Commission representative has made an inspection of the location
and found it to be cleared to comply with Commission Rules and Regulations. Please check
each item in the space provided to indicate that the work has been done.
() 1. All pits have been filled and leveled.
() 2. Rat hole and cellar have been filled and leveled.
() 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, township, and range numbers which have been permanently stenciled or welded on the marker.
() 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and squipment.
() 5. The dead men and tie downs have been cut and removed.
() 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk and equipment.
The above are minimum requirements and no plugging bond will be cancelled until all
locations for plugged and abandoned wells have been inspected and Forms C-103 approved.
When all of the work outlined above has been done, please notify this office by filling
in the blank form below and returning this letter to us so that our representative will
not have to make more than one trip to the location.
OIL CONSERVATION COMMISSION
cc-OCC, Santa Fe
FILL IN BELOW AND RETURN
I certify that the above work has been done and the
is ready for your inspection and approval. Lease Well NoUnit S-T-R
Operator