

NO. OF COPIES RECEIVED
DISTRIBUTION
SANTA FE
FILE
U.S.G.S.
LAND OFFICE
OPERATOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.  
L-275

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Ard Drilling Company	8. Farm or Lease Name Hudson-State
3. Address of Operator P. O. Box 1030 - Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE East LINE AND 660 FEET FROM THE South LINE, SECTION 1 TOWNSHIP 10-S RANGE 32-E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4185 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well Plugged and Abandoned 2-26-72, as follows:  
 Set Cast Iron Bridge Plug on Wire Line at 8695', above perforations at 8802 to 8818' and 8892 to 8902'.  
 Set 50 sack cement plug at 7488', 5-1/2" casing cut-off.  
 Set 35 sack cement plug at 5300'.  
 Set 50 sack cement plug at 3332'.  
 Set 35 sack cement plug at 650', 8-5/8" casing cut-off.  
 Set 35 sack cement plug at 390', bottom of 12-3/4" casing.  
 Set 10 sack cement plug at surface.  
 Regulation Dry Hole Marker Set  
 Heavy Mud Between All Plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE General Manager DATE March 1, 1972

APPROVED BY [Signature] TITLE INSPECTOR DATE 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 21 1954

OIL CONSERVATION COMM.  
HOBBS, N. M.