

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 069300

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mobil Atlantic Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Allison

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3 T9S R36E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Discovery Operating, Inc.

3. ADDRESS OF OPERATOR

504 Gulf Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FS & EL Section 3, T-9-S R-36-E Unit J

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

D F 4104'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Rec completion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. Set Bridge Plug @ 9700' w/3 sacks cement on top of plug.
2. Set 25 sacks of cement 7450-7550'.
3. Cut casing and pulled 5870' 4 1/2" casing.
4. Set 35 sacks of cement 5820-5920'.
5. Set 35 sacks of cement 5550-5650'.
6. Set 35 sacks of cement 4150-4250' (Base of 8 5/8' csg. @ 4200').
7. Cut and pulled 1037' 8 5/8" casing.
8. Set 50 sacks of cement 993-1093'.
9. Set 50 sacks of cement 347-447' (Base of 12 3/4" csg @ 400').
10. Set 10 sacks of cement @ surface.
11. Install marker; fill cellar and pits, level battery grade and remove junk and
clean location. Hole is loaded with brine containing 25 sacks gel per 100 barrels.

Completed plugging 8/26/74. Finished clean-up during 1975.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Vice-President

DATE

3/10/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side