

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instruction, reverse side)Form approved
Budget Bureau No. 47-21424
5. LEASE DESIGNATION AND SERIAL NO.

NM40202771-A

6. IF INDIAN, ALLOTTEE OR TRIBAL, SAY:

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | | |
|---|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | | 7. UNIT AGREEMENT NAME NA |
| 2. NAME OF OPERATOR Stallworth Oil & Gas, Inc. | | 8. FARM OR LEASE NAME Vada Pruitt |
| 3. ADDRESS OF OPERATOR P.O. Box 3310 - Midland, Texas 79701 | | 9. WELL NO. 1 |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter E, 660' From West Line, 1980' From North Line, Section 1, Township 9-S, Range 34-E, N.M.P.M. | | 10. FIELD AND POOL, OR WILDCAT Vada (Penn) |
| 14. PERMIT NO. | | 11. SEC., T., R., or BLM, AND SURVEY OR AREA Sec. 1, T-9-S, R-34-E N.M.P.M. |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4242' KB 4230' GL | | 12. COUNTY OR PARISH 13. STATE Lea New Mexico |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| TEST WATER SHUT-OFF <input type="checkbox"/> | PULL OR ALTER CASING <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | MULTIPLE COMPLETE <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | ABANDON* <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| (Other) <input type="checkbox"/> | |

SUBSEQUENT REPORT OF:

| | |
|--|--|
| WATER SHUT-OFF <input type="checkbox"/> | REPAIRING WELL <input type="checkbox"/> |
| FRACTURE TREATMENT <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| SHOOTING OR ACIDIZING <input type="checkbox"/> | ABANDONMENT* <input checked="" type="checkbox"/> |
| (Other) <input type="checkbox"/> | |

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log forms.)

17. SUMMARY OF COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and completion, if well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plugging Operations: Set cast iron bridge plug with 35' cement plug on top at 9600'. Set cast iron bridge plug with 35' cement plug on top at 7700'. Shot 5-1/2" csg. at 6970' - Unable to load hole. Pumped 50 sack cement plug at 6500' as per instructions of Mr. Arthur Brown, 7-29-76. Shot casing at 4028' - Removed from well. Spotted 40 sack cement plug from 4079' to 3939' via 2-3/8" tbg. Hole loaded with brine & salt gel. Shot 8-5/8" casing at 684' - Removed from well. Spotted 70 sack cement plug at 440'. Top at 330'. Hole loaded with brine & salt gel. Set 10 sack cement plug at surface. Install dry hole marker as per requirement. Will advise when well site ready for final inspection. Above work completed 8-3-76.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Robert V. Mansub*TITLE Field SuperintendentDATE 8/10/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side