

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-494
7. Unit Agreement Name
8. Farm or Lease Name Midwest - State
9. Well No. #1
10. Field and Pool, or Wildcat Vada-Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator Hanson Oil Corporation
3. Address of Operator P. O. Box 1515, Roswell, New Mexico, 88201
4. Location of Well UNIT LETTER <u>P</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>9-S</u> RANGE <u>33-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4340' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3-26-79 Set Wireline Bridge Plug @ 9430'.
- 3-27-79 Spotted 6 sk plug on top of BP from 9430-9390'.
- 3-30-79 Shot 5½" pipe off @ 5395'.
- 4-02-79 Spotted 50 sx cmt from 5445-5222' - Spotted 60 sx cmt from 4312-4212'.
- 4-03-79 Shot 8-3/8" pipe off (900').
- 4-04-79 Spotted 60 sk cmt plug from 950-840' - Spotted 65 sk cmt plug from 450-350'.
- 4-05-79 Pumped 30 sk plug from 50-0'- Put up Dry Hole Marker - P&A on 4-5-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Goname R Schmitt</u>	TITLE <u>Production Clerk</u>	DATE <u>4/6/79</u>
APPROVED BY <u>W. J. Hartman</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JAN 16 1981</u>

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 11 1979
OIL CONSERVATION COMM.
HOBBS, N. M.