Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Natural Resources Department

Form C-103

Revised 1-1-89

| P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION D | IVISION WELL API NO. |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 8750 | 4_2088 30-025-24181 |
| P.O. Drawer DD, Artesia, NM 88210 | 5. Indicate Type of Lease STATE FEE X |
| DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 | 6. State Oil & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS | |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | LUG BACK TO A 7. Lease Name or Unit Agreement Name |
| 1. Type of Well: OIL | U. D. Sawyer |
| 2. Name of Operator | 8. Well No. |
| Oryx Energy Company 3. Address of Operator | 9. Pool name or Wildcat |
| P. O. Box 1861, Midland, Texas 79702 | Crossroads Siluro Devonian |
| Unit Letter <u>B</u> : <u>990</u> Feet From The <u>North</u> Section 27 Township 9-S Range 3 10. Elevation (Show whether DF, RK) 4031.5 GR | Line and 2310 Feet From The East Line 36-E NMPM Lea County B, RT, GR, etc.) |
| 11. Check Appropriate Box to Indicate Nature | e of Notice, Report, or Other Data |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REM | EDIAL WORK ALTERING CASING |
| TEMPORARILY ABANDON CHANGE PLANS COM | IMENCE DRILLING OPNS. PLUG AND ABANDONMENT |
| NIII OD ALTER CACING | ING TEST AND CEMENT JOB |
| OTHER:OTH | |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pwork) SEE RULE 1103. | vertinent dates, including estimated date of starting any proposed |
| 1/26/90 MIRU KWA Well Svc. | |
| 1/27-1/31/90 Drld & cleaned out Iron Sulfide. | |
| 2/1/90 Hole caving in. | |
| POH to 2100' spot 35 sk cmt plug from 2 | o 4344', spot 35 sk cmt plug from ug at 4255', mix & spot 10 sk cmt plug, 100' to 2000' |
| 2/3/90 Fin POH w/tbg, dig out cellar, break ou pipe, cut pipe at 824', pull & LD 160' | t wellhead, weld on lift nipple, work csg. |
| | ContinuedPage 2 |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief. | |
| SIGNATURE Marin J. Flore TITLE Pr | oration Analyst |
| TYPEOR PRINT NAME Maria L. Perez | <u>теје</u> рноне но. 915-688-03 |
| (This space for State Use) | 715-000-03 |
| | s gas inspector May > 3 19 |
| APPROVED BY Jack Striffin TITLE | DATE |
| CONDITIONS OF APPROVAL, IP ANY: | |