

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Sun Exploration & Production Co.

3. Address of Operator
P. O. Box 1861, Midland, Texas 79702

4. Location of Well
UNIT LETTER H 1980 FEET FROM THE north LINE AND 990 FEET FROM
THE east LINE, SECTION 27 TOWNSHIP 9-S RANGE 36-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
U. D. Sawyer

9. Well No.
9

10. Field and Pool, or Wildcat
Crossroads, Penn

15. Elevation (Show whether DF, RT, GR, etc.)

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2-29-84 MIRU. Caffey WS dug out cellar ND wellhead NU BOP rel. pkr. POH w/2-7/8 tbg.
- 2-30-84 FOH w/7" pkr. TIH w/7" CIBP on 2-7/8 tbg set CIBP at 10495'. Circ hole w/10# mud.
- 1-85 Spot 25 sxs cmt plug from 10495-10440, POH to 9302, spot 25 sxs cmt plug 9302-9169, POH w/2-7/8 WS, nipple dwn wellhead to 7" csg, weld on lift sub, installed hyd jacks, work 7" csg for 1 hr.
- 2-85 Rig dwn jacks, cut off 7" lift nipple, NU BOP, RIH w/2-7/8 WS open end to 7747, spot 25 sxs cmt plug 7747-7614, POH w/2-7/8 WS, ND BOP & head, weld on 7" nipple, install jacks.
- 4-85 Cathy WL. Ran 7" Jet cutter & cut 7" csg @ 5540.
- 5-85 RIH w/2-7/8 WS. Open ended to 5581, circ hole w/10.0 ppg mud, Cathy spot 50 sxs Class "C" cmt plug 5581-5413.
- 6-85 Lwr & tag cmt plug @ 5430, PU & Cathy spotted 50 sxs Class "C" cmt plug 4300-4166, PU to 2300.
- 8-85 Lower & tag cmt plug @ 4175, Pull up to 2257, spot 50 sxs cmt plug 2257-2125, POH w/2-7/8WS Perf 4 sqz holes @ 350, RIH w/9-5/8 AD-1 pkr on 2-7/8 WS to 150', est circ thru sqz holes @ 350', circ between 9-5/8 & 13-3/8 csg out bradenhead, pump 65 sxs Class "C" cmt thru holes @ 350', displaced to 250'.
- 9-85 Test plug to 500# rel AD-1 pkr POH LD WS & pkr cut off csg 4' BGL mix 10 sxs cmt plug. Spot in surf, install dryhole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Velma Reyes

TITLE Senior Accounting Asst.

DATE 1-21-85

APPROVED BY Ra Lallu

TITLE F.P.

DATE 3-18-85

CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTOR

MAR 18 1985