

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-274

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Bridwell Oil Company	8. Farm or Lease Name N.M. 8 State
3. Address of Operator P. O. Box 2038, Abilene, Texas 79604	9. Well No. 2
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>9-S</u> RANGE <u>33E</u> N.M.P.M.	10. Field and Pool, or Wildcat Flying "M" San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4386 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & Abandonment Operations 7-29-80 thru 8-2-80

7-29-80 MIRU DA&S Unit #832. Pull Rods & tubing.  
7-30-80 Run CIBP & Set @ 4400' w/35' cement on top. Circulated hole w/10.2ppg mud.  
7-31-80 Free point casing. Shot @ 1500'. Spotted 12 sx plug @ 1900'.  
Spotted 50 sx plug @ 1550'  
8-1-80 Tagged plug @ 1432'. Pulled tubing to 416', mixed 75 sx plug. Waited 4 hrs.  
Tried to tag plug. Plug was not in place. Pumped another 75 sx plug.  
8-2-80 Tagged plug @ 200'. Spotted 15sx plug @ surface w/dry hole marker.  
Cleaned location. Pits filled. Location leveled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. J. Layford TITLE Prod. Supt. DATE 9-2-80

APPROVED BY A. H. Stutts TITLE OIL & GAS INSPECTOR DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: