

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR NOTICES TO ABANDON OR TO PERMIT CHANGING FROM ONE RESERVOIR TO ANOTHER. USE APPLICATION FOR PERMIT TO PRODUCE OIL, GAS, OR GEOTHERMAL FLUIDS.

1. Name of Operator
V-F Petroleum Inc.

2. Address of Operator
One Marienfeld Place, Suite 580, Midland, Texas 79701

3. Location of Well
UNIT LETTER **P** **519** FEET FROM THE **South** LINE AND **519** FEET FROM THE **East** LINE, SECTION **32** TOWNSHIP **9-S** RANGE **37-E** NMPL.

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
K-6857

7. Unit Agreement Name

8. Farm or Lease Name
State 32

9. Well No.
1

10. Field and Pool, or Wildcat
West Sawyer, San Andres

12. County
Lea

13. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-15-83. MIRUPU. Attempt to pull tbg - would not move. RU CRC Western - run free point - no movement below 2907'. GIH w/chemical cutter - cut off tbg @ 4900'. GIH w/2nd cutter - cut off tbg at 2871'. POH w/2871' of 2-3/8" tbg.

4-16-83. GIH w/overshot, jars, bumper sub & 6 D.C.s. Latch onto 2-3/8" tbg - jar for 3-1/2 hrs - no movement. Release overshot & POH. SDON.

4-17-83. SD on Sunday.

4-18-83. GIH w/6 jts wash pipe, 6 D.C.s, & 2-3/8" tbg. Wash over fish to 2907'. Recover sand, scale & red shale. Could not make hole below 2907'. POH w/ wash pipe. GIH w/wash pipe w/cut-rite shoe. Mill from 2907' to 2913' - recover metal cuttings, red shale & sand. SDON.

4-19-83. POH w/wash pipe & mill. GIH w/mill & wash pipe. Mill from 2913' to 2919'. POH w/mill. SDON.

4-20-83. GIH w/mill & wash pipe. Mill from 2919'-2924'. POH. GIH w/mill - mill from 2924' to 2927'. SDON

4-21-83. Mill from 2927'-2931'. POH w/mill. GIH w/mill - could not get below 2907'. POH w/wash pipe & mill. GIH w/overshot. Latch onto fish at 2871'. Jar one time. POH w/overshot - recover cut-off tbg stub & 1 full jt w/collar on bottom. Collar was milled on one side. SDON.

Continued on attached page

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. Engler TITLE Operations Manager DATE May 25, 1983

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE MAY 27 1983

CONDITIONS OF APPLICATION Expires 11/27/83