

O. C. COPIES RECEIVED		
DISTRIBUTION		
NTA FE		
E		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dryhole</p> <p>2. Name of Operator Coastal States Gas Producing Company</p> <p>3. Address of Operator P. O. Box 235, Midland, Texas 79701</p> <p>4. Location of Well UNIT LETTER F, 1969 FEET FROM THE north LINE AND 2000 FEET FROM THE west LINE, SECTION 9 TOWNSHIP 9-S RANGE 33-E NMPM.</p>		<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name State 9</p> <p>9. Well No. 2</p> <p>10. Field and Pool, or Wildcat Flying "M" San Andres</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4380.9 GR</p>		<p>12. County Lea</p>

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p> <p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>SUBSEQUENT REPORT OF:</p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	
--	--	--	--

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-7-74

1. Set 40 sx. plug @ 4500-4430'. WOC 12 hrs.
2. Set 35 sx. plug @ 2800-2700'.
3. Set 35 sx. plug @ 1700-1600'.
4. Set 35 sx. plug @ 386-286'.
5. Set 10 sx. plug @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J.B. Shepherd* TITLE Dist. Prod. Superintendent DATE 8-12-74

APPROVED BY *A.G. Patterson* TITLE OIL & GAS INSPECTOR DATE JUL 9 1980

CONDITIONS OF APPROVAL, IF ANY: