Submit 3 Copies to Appropriate
District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 **Revised 1-1-89**

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II .
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

ack Griffin

CONDITIONS OF APPROVAL, IF ANY:

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-24855

5. Indicate Type of Lease

STATE FEE

SUNDRY MOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM ROS PROPOSALS TO DRILLO BY DO ESPEN OR PLUG BACK TO A DIFFERENT RESERVORR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS. 1. Type of Well:	1000 Rio Brazos R	Rd., Aziec, NM 87410	6. State Oil & Gas Lease No. LG1736	
One Will Company 2. Name of Operator 2. Name of Operator 2. Name of Operator 3. Address of Operator 3. Address of Operator 3. Address of Operator 104 S. Peccos, Midland, TX 79701 4. Well Location Unit LetterI :2080 Feet From TheSouth	(DO NOT USE	THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		
A Address of Operator 104 S. Pecos, Midland, TX 79701 4. Well Location Unit Letter	1. Type of Well: OIL WELL XX		Hugh 689-C	
1. N Bagley, Permo Penn 4. Well Location Unit Letter I : 2080 Feet From The South Line and 560 Feet From The East Line Section 6 Township 12-5 Range 33E NMFM Lea County 10. Elevation (Show whether DF, RRB, RT, GR, etc.) 4294' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed worth) SEE RULE 1103. 10-7-91 TD 10,400, Spotted 25 sx plug @ 8500'. Tagged @ 7936'; shot 5-1/2" csg @ 4000'; attmepted to work free & csg parted @ 3660', LD 311 jts (3645') of 5-1/2" csg. 10-8-91 Spotted 75 sx plug @ 4050', tagged @ 3565', shot 8-5/8" csg @ 860', LD 38 jts (862.25') of 8-5/8". 10-9-91 Spotted 75 sx @ 910', tagged @ 716', Spotted 100 sx @ 430' tagged @ 274'. Spotted 15 sx @ surface. Installed dry hole marker. P & A 10-9-91 Thereby certify that the Information sprife is true and produce to the best of any provided each detail. TITLE Regulatory Administrator parts 10-14-91			8. Well No.	
Unit Letter I: 2080 Feet From The South Line and 560 Feet From The East Line Section 6 Township 12-S Range 33E NMFM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4294' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENT COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENT COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENT COMMEN	104 S. Pe	ecos, Midland, TX 79701		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4294 GR			560 Feet From The East Line	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 10-7-91 TD 10,400, Spotted 25 sx plug @ 8500'. Tagged @ 7936'; shot 5-1/2" csg @ 4000'; attmepted to work free & csg parted @ 3640', LD 111 jts (3645') of 5-1/2" csg. 10-8-91 Spotted 75 sx plug @ 4050', tagged @ 3565', shot 8-5/8" csg @ 860', LD 38 jts (862.25') of 8-5/8". 10-9-91 Spotted 75 sx @ 910', tagged @ 716', Spotted 100 sx @ 430' tagged @ 274'. Spotted 15 sx @ surface. Installed dry hole marker. P & A 10-9-91 Thereby certify that the information phote is true and proplete to the best of any provincing and balled. Thus. Regulatory Administrator DATE 10-14-91	Section	10. Elevation (Show whether DF, RKB, RT, GR, etc.		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 10-7-91		Check Appropriate Box to Indicate Nature of Notice	-	
CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: ID-7-91 TD 10,400, Spotted 25 sx plug @ 8500'. Tagged @ 7936'; shot 5-1/2" csg @ 4000'; attmepted to work free & csg parted @ 3640', LD 111 jts (3645') of 5-1/2" csg. 10-8-91 Spotted 75 sx plug @ 4050', tagged @ 3565', shot 8-5/8" csg @ 860', LD 38 jts (862.25') of 8-5/8". 10-9-91 Spotted 75 sx @ 910', tagged @ 716', Spotted 100 sx @ 430' tagged @ 274'. Spotted 15 sx @ surface. Installed dry hole marker. P & A 10-9-91 Thereby certify that the information shorts is true and possible to the boat of any knowledge and boiled. Signature Thus Regulatory Administrator DATE 10-14-91	PERFORM REME	EDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K ALTERING CASING	
OTHER: OTHER: OTHER: OTHER: OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 10-7-91 TD 10,400, Spotted 25 sx plug @ 8500'. Tagged @ 7936'; shot 5-1/2" csg @ 4000'; attmepted to work free & csg parted @ 3640', LD 111 jts (3645') of 5-1/2" csg. 10-8-91 Spotted 75 sx plug @ 4050', tagged @ 3565', shot 8-5/8" csg @ 860', LD 38 jts (862.25') of 8-5/8". 10-9-91 Spotted 75 sx @ 910', tagged @ 716', Spotted 100 sx @ 430' tagged @ 274'. Spotted 15 sx @ surface. Installed dry hole marker. P & A 10-9-91 Thereby certify that the information spoyle is true and surplace to the best of my trowledge and boild. SIGNATURE TIME Regulatory Administrator DATE 10-14-91	TEMPORARILY A	ABANDON CHANGE PLANS COMMENCE DRI	ILLING OPNS. PLUG AND ABANDONMENT	
12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 10-7-91 TD 10,400, Spotted 25 sx plug @ 8500'. Tagged @ 7936'; shot 5-1/2" csg @ 4000'; attmepted to work free & csg parted @ 3640', LD 111 jts (3645') of 5-1/2" csg. 10-8-91 Spotted 75 sx plug @ 4050', tagged @ 3565', shot 8-5/8" csg @ 860', LD 38 jts (862.25') of 8-5/8". 10-9-91 Spotted 75 sx @ 910', tagged @ 716', Spotted 100 sx @ 430' tagged @ 274'. Spotted 15 sx @ surface. Installed dry hole marker. P & A 10-9-91 Thereby certify that the information shopic is true and appliede to the best of any two wholege and belief. SIONATURE TIME Regulatory Administrator DATE 10-14-91	PULL OR ALTER	CASING CASING TEST A	ND CEMENT JOB	
10-7-91 TD 10,400, Spotted 25 sx plug @ 8500'. Tagged @ 7936'; shot 5-1/2" csg @ 4000'; attmepted to work free & csg parted @ 3640', LD 111 jts (3645') of 5-1/2" csg. 10-8-91 Spotted 75 sx plug @ 4050', tagged @ 3565', shot 8-5/8" csg @ 860', LD 38 jts (862.25') of 8-5/8". 10-9-91 Spotted 75 sx @ 910', tagged @ 716', Spotted 100 sx @ 430' tagged @ 274'. Spotted 15 sx @ surface. Installed dry hole marker. P & A 10-9-91 P & A	OTHER:	OTHER:		
Tagged @ 7936'; shot 5-1/2" csg @ 4000'; attmepted to work free & csg parted @ 3640', LD 111 jts (3645') of 5-1/2" csg. 10-8-91	12. Describe Propo work) SEE RU	osed or Completed Operations (Clearly state all pertinent details, and give pertinent dates ULE 1103.	, including estimated date of starting any proposed	
(862.25') of 8-5/8". 10-9-91 Spotted 75 sx @ 910', tagged @ 716', Spotted 100 sx @ 430' tagged @ 274'. Spotted 15 sx @ surface. Installed dry hole marker. P & A 10-9-91 I hereby certify that the information above is true and somplete to the best of my provviedge and belief. Signature	10-7-91	Tagged @ 7936'; shot 5-1/2" csg @ 4000'; attmepted to work free & csg parted		
Spotted 15 sx @ surface. Installed dry hole marker. P & A 10-9-91 I hereby certify that the information shows is true and somplete to the best of my knowledge and belief. Signature The Regulatory Administrator Date 10-14-91	10-8-91			
I hereby certify that the information above is true and stoppiete to the best of my knowledge and belief. SIGNATURE LEGISLAT BLAND TIME Regulatory Administrator DATE 10-14-91	10-9-91			
SIGNATURE SECURITY SUMMER REGulatory Administrator DATE 10-14-91		P & A 10-9-91		
SIGNATURE SECURITY SUMMER REGulatory Administrator DATE 10-14-91	· · · · · · · · · · · · · · · · · · ·			
TYPE OR PRINT NAME Dorothy Houghton TELEPHONE NO 915_682_37			y Administrator DATE 10-14-91	
The distriction of the state of	TYPE OR PRINT NAM	ME Dorothy Houghton	TELEPHONE NO. 915-682-375	

CIL & GAS INSPECTOR

FEB 06'92