

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
OG 4983

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <i>Lea</i> Petroleum Corp.	8. Farm or Lease Name Zapata State
3. Address of Operator P. O. Drawer 2358, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER <u>H</u> , <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>10</u> TOWNSHIP <u>10-S</u> RANGE <u>32 E</u> NMPM.	10. Field and Pool, or Wildcat N. Mescalero Cisco
15. Elevation (Show whether DF, RT, GR, etc.) 4345 G 4361 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP at 8750 and capped it with 35 ft. of cement.
2. RIH with tbg. and circ. hole with mud laden fluid.
3. Cut 5½ csg. 5467 ft. POH.
4. RIH with tbg. to 5507 ft. and spotted 100 sax plug. Tagged plug at 5180.
5. Pulled tbg. to 3512. Spotted 60 sax plug. Tagged at 3380 ft.
6. Shot 8-5/8 csg. at 838 ft. POH.
7. Pumped a 75 sax at 888. Tagged at 750 ft.
8. Pumped a 80 sax plug at 402 to 302 and POH .
9. Cut off well head. Spotted surf. plug and installed dry hole marker. Rigged down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *W. C. [Signature]* TITLE Agent DATE 12-13-78
APPROVED BY *Jesli V. Clements* TITLE OIL & GAS INSPECTOR DATE JUN 26 1980
CONDITIONS OF APPROVAL, IF ANY: