

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.		7. Unit Agreement Name
6. Name of Operator Sage Energy Company		
7. Address of Operator P. O. Drawer 3068, Midland, Texas. 79702		8. Farm or Lease Name Thorton-State
8. Location of Well UNIT LETTER <u>0</u> <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>330</u> FEET FROM THE <u>South</u> LINE, SECTION <u>3</u> TOWNSHIP <u>10S</u> RANGE <u>32E</u> NMPM.		9. Well No. <u>1</u>
10. Elevation (Show whether DF, RT, GR, etc.) <u>4331'</u>		10. Field and Pool, or Wildcat N. Mescarlero-Cisco
12. County Lea		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>
1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			

Set Cast Iron Bridge Plug and 25 feet cement at 8900';
 Set 100' plug at 7190';
 Set 100' plug at 8345';
 Set 100' plug at 7190';
 Cut 4½" csg at 7000';
 Set 100' plug on top of 4½" stub;
 Set 100' plug at 4850' in 7 7/8" hole;
 Set 100' plug at 3450' at bottom of 8 5/8";
 Cut off 8 5/8", set 100' plug at 2300';
 Set 100' plug at 2010' in 11" hole;
 Set 100' plug at 1550' in 11" hole;
 Set 100' plug at 399' in 12 3/4" hole;
 Set 10 sxs surf. plug.

Plugging operation to begin on approval by the New Mexico Oil Conservation Commission.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>[Signature]</u>	TITLE <u>Production Superintendent</u>	DATE <u>2-14-84</u>	
APPROVED BY <u>ORIGINAL SIGNED BY JERRY SEXTON</u> <u>DISTRICT I SUPERVISOR</u>		DATE <u>FEB 17 1984</u>	
CONDITIONS OF APPROVAL, IF ANY:			

200-111111
FEB 16 1984
C.C.D.
HOBBS OFFICE