

COPIES RECEIVED	
DISTRIBUTION	
SA A FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tri-Service Drilling Company	8. Farm or Lease Name Santa Fe
3. Address of Operator P. O. Drawer 70 - Midland, Texas	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>990 East</u> LINE, SECTION <u>20</u> TOWNSHIP <u>9-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4057' GR	12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-3-75 30 sacks @ 11,400' T.D.  
30 sacks @ 9300-9400  
30 sacks @ 9000-9100  
30 sacks @ 7650-7750  
30 sacks @ 5450-5550  
30 sacks @ 4150-4250  
30 sacks @ Cut off of 8-5/8"  
30 sacks @ Base of surf. 365-465  
10 sacks @ Surface.

→ 100' plug at shoe of 8 5/8" casing  
& 100' plug at tip of sett if not behind pipe.  
24 hour notice to o.c.c. before setting bottom plug.  
9.5# mud between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>N. W. Allen</u>	TITLE <u>Prod. Supt.</u>	DATE <u>4-4-75</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>APR 8 1975</u>
CONDITIONS OF APPROVAL, IF ANY:		