

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Shell Petroleum Corp. 9208	8. Farm or Lease Name Alice Ann A 16120
3. Address of Operator P. O. Box 2358, Midland, Texas 79701	9. Well No. 1 24620
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 9-S RANGE 32-E NMPM.	10. Field and Pool, or Wildcat Flying M San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4321 GR 4338 KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP at 4175 and capped with 35 ft. cement.
2. Circ. hole with mud laden fluid.
3. Cut csg. at 3416 POH.
4. RIH with tbg. Spotted 65 sax plug at 3477. Tagged at 3262 ft.
5. Shot 8-5/8 csg. at 360 ft. POH with same.
6. Run tbg. to 400 ft. and spotted 100 sax plug.
7. Cut off well head. Installed dry hole marker. Rigged down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H.C. [Signature] TITLE Agent DATE 12-13-78

APPROVED BY A.G. [Signature] TITLE OIL & GAS INSPECTOR DATE JUN 9 1980

CONDITIONS OF APPROVAL, IF ANY: