

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Teal Petroleum Company	8. Farm or Lease Name Alice Ann "A"
3. Address of Operator P.O. Box 2358, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> 1980 FEET FROM THE <u>North</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>9-S</u> RANGE <u>32-E</u> NMPM.	10. Field and Pool, or Wildcat Flying M, Bough, So.
15. Elevation (Show whether DF, RT, GR, etc.) 4321 Gr., 4338 KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Proposed P & A Procedure as Follows:

1. Run 4½", 11.6# CIBP @ 8900' w/3 sx cmt. on plug.
2. Cut-off 4½" csg. @ free point estimated @ 7100'.
3. Load hole w/10# mud.
4. Spot 65 sx cmt. plug @ 7100' (or 4½" csg. stub).
5. Spot 65 sx cmt. plug @ 4930' (Top of Glorieta).
6. Cut-off 8 5/8" @ free point (estimated @ 750'). Pull 8 5/8".
7. Spot 50 sx. cmt. plug @ 800' (or 50' in & out of 8 5/8" stub).
8. Spot 75 sx cmt. plug @ 400' (50' in & out of 12 3/4" csg.).
9. 10 sx plug @ surface.
10. Place 4" x 4" marker @ well w/required information.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Alouise W. Rice TITLE Assistant Dist. Manager DATE July 27, 1976

APPROVED BY Jerry Barton TITLE Dist. L. Manager DATE JUL 29 1976
CONDITIONS OF APPROVAL, IF ANY: