

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

SEP 17 8 23 AM '90

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

KERR MCGEE CORPORATION

3. Address and Telephone No.

P.O. BOX 11050 MIDLAND, TEXAS (915) 688-7000

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2120' FEL & 800' FSL SECTION 23, T-9-S, R-37-E

5. Lease Designation and Serial No.

LC - 065151

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

BILBREY "23" #5

9. API Well No.

30-025-24965

10. Field and Pool, or Exploratory Area

SAWYER, WEST (SAN ANDRES)

11. County or Parish, State

LEA

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other REMEDIAL WORK
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-22-90 MIRU. TOH W/ RODS & PMP. TIH W/ TBG. TAGGED TD @ 5216.64'. SN @ 5090'.
8-23-90 RIH W/ GAUGE RING & JUNK BASKET. PERF 2 SPF FROM 5027 - 5035 (17 HOLES) & 2 SPF 5040 - 5045 (11 HOLES) TOTAL 28 HOLES. PU 4 1/2" RBP W/ BALL CATCHER & 4 1/2" COMP. PKR. TIH ON 2 3/8" TBG. SET RBP @ 5070. POOH TO 5010' & SET PKR. ACID FRAC NEW PERFS 5027 - 45' w/500 GAL 15% DAD, 4500 GAL 20% NEFE & 4500 GAL YF 120 PSG. POOH & SET RBP @ 5010' & PKR @ 4930'. ACIDIZED OLD PERFS 4987' - 96' w/500 GAL 15% DAD & 1500 GAL 15% NEFE. POOH & RESET PKR @ 4930'. STARTED SWAB
8-24-90 SWAB TEST WELL.
8-25-90 TOOH W/ PKR, RBP & TBG. TIH W/ TBG W/ SN @ 5090'. RAN PUMP & RODS, RET. TO PROD.
9-10-90 24 HOUR TEST 9.25 BO & 6.25 BW. PRIOR RATE - 3.5 BOPD & 6.7 BWPD.

14. I hereby certify that the foregoing is true and correct

Signed

Title

Date

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: