

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-035-24996
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-1733

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Bagley State
2. Name of Operator ELK OIL COMPANY	8. Well No. 1
3. Address of Operator Post Office Box 310, Roswell, New Mexico 88202-0310	9. Pool name or Wildcat North Bagley Permo Penn
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>East</u> Line and <u>660</u> Feet From The <u>South</u> Line Section <u>36</u> Township <u>11 South</u> Range <u>32 East</u> NMFM <u>Lea</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4314 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

04/06/89: Set CIBP @ 8710', dump 35' cement on top.
Circulate hole @ 10# mud.
04/07/89: Spot 25 sxs @ 5850'-5650'.
04/10/89: Pull 3784' of 5½" casing.
04/10/89: Spot 50 sxs @ 3834', tag @ 3705'.
04/11/89: Pull 979' of 8 5/8" casing.
04/11/89: Spot 70 sxs @ 1030', tag @ 900'.
04/11/89: Spot 70 sxs @ 397', tag @ 230'.
04/11/89: Spot 10 sxs @ surface.
Install dry hole marker.

READY FOR INSPECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joseph J. Kelly TITLE President DATE 10/08/90
TYPE OR PRINT NAME Joseph J. Kelly TELEPHONE NO. 623-3190

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE OCT 10 1990
CONDITIONS OF APPROVAL, IF ANY:

NR E

RECEIVED

OCT 09 1980

OCD
HOBBS OFFICE