

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator McMurren Exploration Company
3. Address of Operator 3400 Plaza Tower, New Orleans, La. 70113
4. Location of Well UNIT LETTER <u>A</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>Last</u> LINE, SECTION <u>31</u> TOWNSHIP <u>11S</u> RANGE <u>35E</u> NMPLA.
15. Elevation (Show whether DF, RT, GR, etc.)

7. Unit Agreement Name
8. Farm or Lease Name State 31
9. Well No. 1
10. Field and Pool, or Wildcat UNDEVELOPED
12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug at 9400'.
Capped with 35' of cement
Cut and pulled 5-1/2" casing from 2981'.
Loaded hole with mud.
Set 35 sack cement plug from 3017' to 2917'.
Cut and pulled 5-5/8" casing from 295'.
Set 75 sack cement plug from 350' to 250'.
Set 10 sack cement plug at surface.
Installed dry hole marker.
Cleaned and leveled location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ken Lempford</u>	TITLE <u>Agent</u>	DATE <u>3/19/76</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		