

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-6657	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Hanson Oil Corporation		8. Farm or Lease Name Amoco State
3. Address of Operator P.O. Box 1515, Roswell, New Mexico 88201		9. Well No. #3
4. Location of Well UNIT LETTER <u>I</u> <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>10</u> TOWNSHIP <u>9-S</u> RANGE <u>33-E</u> NMPM.		10. Field and Pool, or Wildcat Flying "M" ABO
15. Elevation (Show whether DF, RT, GR, etc.) 4364 GL		12. County Lea

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Plug back and recompletion

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-11-75 Set Wireline Bridge Plug @ 9490'. Dumped 35' of cement on top of plug

11-12-75 Set Wireline Bridge Plug @ 9090'. Dumped 35' of cement on top of plug. Perforated 2 shots per foot @ 8685-92', 8696-98', 8700-06'. Run pkr. to 8500', acidized w/ 1500 gal Mod 202 acid.

11-13-75 Swabbed well 8 hours.

11-14-75 Run Free type pump and put well on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ray M. Hill TITLE Vice President/Production DATE 1/20/76

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE Mar 9

CONDITIONS OF APPROVAL, IF ANY: