	PARTMENT			
NO. 47 COMIES RECEIVED	L CONSERVATION DIVISION	·		
DISTRIBUTION	P. O. BOX 2088	Form C-103 Revised 10-1-7:		
SANTA FE	SANTA FE, NEW MEXICO 87501			
PILZ	<u></u>	5a. Indicate Type of Lease		
U.1.G.S.		State Fee X		
LAND OFFICE		5. State Oll & Gus Lease No.		
OPERATOR		State On a Geatleday Not		
	API NO. 30-025-25027			
(00 NOT USE THIS FOR USE	SUNDRY NOTICES AND REPORTS ON WELLS			
OIL GAB	X	7. Unit Agreement Name		
Name of Operator		B. Farm or Lease Name		
Dhilling Dotrol	cum Compone			
Phillips Petrol Address of Operator		Marg C "Com"		
•		3. Weiz 140.		
	Penbrook St., Odessa, TX 79762	1		
, Location of Well		10. Field and Pool, or Wildcat		
UNIT LETTER N	660 FEET FROM THE South 1980 FEET FROM	South Flying M Atoka		
West	IE, SECTION 24 TOWNSHIP 9-S RANGE 32-E NMPM.	$\boldsymbol{\chi}_{\boldsymbol{i}}(\boldsymbol{i}) = \boldsymbol{\chi}_{\boldsymbol{i}}(\boldsymbol{i}) = \boldsymbol{\chi}$		
THE LI	E, SECTION TOWNSHIP RANGE JZ-E NMPM.			
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County		
	4341' GR, 4353' DF, 4354' RKB	Lea AIIIIIII		
^{د.} (Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data		
	· · · · ·	REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	••••••••••••••••••••••••••••••••••••••		
8		ALTERING CASING		
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT		
PULL OR ALTER CABING	CHANGE PLANS			
	OTHER			
OTHER				
 Describe Proposed or Com work) SEE RULE 1103. 	pleted Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed		
WURN SEE NOLE 1103		catinuted dute of starting any proposed		
		estimated date of starting any proposed		
9-10-80	MI Jamison and Caffey. Set BP at 10,400'. Dmpd 3 sx			
	MI Jamison and Caffey. Set BP at 10,400'. Dmpd 3 sx Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a	s cmt on plug.		
9–10–80 9–11–80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a	s cmt on plug.		
9-11-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg.	s cmt on plug.		
9-11-80 9-12/15-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg.	s cmt on plug. t 10,360' and 75		
9-11-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6	s cmt on plug. t 10,360' and 75		
9-11-80 9-12/15-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg.	s cmt on plug. t 10,360' and 75 hrs. Tagged plug		
9-11-80 9-12/15-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg.	s cmt on plug. t 10,360' and 75 hrs. Tagged plug		
9-11-80 9-12/15-80 9-16-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'.	s cmt on plug. t 10,360' and 75 hrs. Tagged plug		
9-11-80 9-12/15-80 9-16-80 9-17-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg.	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs.		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'.		
9-11-80 9-12/15-80 9-16-80 9-17-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'.	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80	Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs.	hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80	<pre>Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at</pre>	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80	Prep to pull $5-1/2"$ csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off $5-1/2"$ csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at at 450'. WOC 4 hrs. Tagged TOC at 280'. Spotted 75	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs sxs at 100' and		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80	<pre>Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at at 450'. WOC 4 hrs. Tagged TOC at 280'. Spotted 75 circd to surf. MO Jamison and Caffey. Installed dry</pre>	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs sxs at 100' and		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80	Prep to pull $5-1/2"$ csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off $5-1/2"$ csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at at 450'. WOC 4 hrs. Tagged TOC at 280'. Spotted 75	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs sxs at 100' and		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80	<pre>Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at at 450'. WOC 4 hrs. Tagged TOC at 280'. Spotted 75 circd to surf. MO Jamison and Caffey. Installed dry</pre>	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs sxs at 100' and		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80 9-20-80	<pre>Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at at 450'. WOC 4 hrs. Tagged TOC at 280'. Spotted 75 circd to surf. MO Jamison and Caffey. Installed dry Well P&A 9-20-80.</pre>	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs sxs at 100' and hole marker.		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80 9-20-80 BOP Equipment Se	<pre>Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at at 450'. WOC 4 hrs. Tagged TOC at 280'. Spotted 75 circd to surf. MO Jamison and Caffey. Installed dry Well P&A 9-20-80.</pre>	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs sxs at 100' and hole marker.		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80 9-20-80	<pre>Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at at 450'. WOC 4 hrs. Tagged TOC at 280'. Spotted 75 circd to surf. MO Jamison and Caffey. Installed dry Well P&A 9-20-80.</pre>	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs sxs at 100' and hole marker.		
9-11-80 9-12/15-80 9-16-80 9-17-80 9-18-80 9-19-80 9-20-80 BOP Equipment Se manually operate	<pre>Prep to pull 5-1/2" csg. Spotted 75 sxs Cl "C" cmt a sxs at 9410'. Pulled tbg. Cut off 5-1/2" csg at 6200'. Pulled 6200' of csg. Ran tbg to 6250'. Spotted 70 sxs Cl "H" cmt. WOC 6 at 6110'. Pulled tbg. Ran 2-3/8" tbg and 8-5/8" cmt ret. Set ret at 8735'. Pulled tbg. Pulled 8-5/8" csg. Welded 8-5/8" pull npl. Cut 8-5/ Pulled 1200' of 8-5/8" csg. Ran 2-3/8" tbg to 1870'. Cl "C" cmt at 1870' and 75 sxs at 1250'. WOC 14 hrs. Tagged plug at 1135'. Spotted 150 sxs Cl "C" cmt at at 450'. WOC 4 hrs. Tagged TOC at 280'. Spotted 75 circd to surf. MO Jamison and Caffey. Installed dry Well P&A 9-20-80.</pre>	s cmt on plug. t 10,360' and 75 hrs. Tagged plug Cmtd w/150 sxs. 8" csg at 1200'. Spotted 50 sxs 1000' and 150 sxs sxs at 100' and hole marker.		

	TITLE _	Sr. Engineering Specialist	DATE	9-23-80
APPROVED BY AND TRACTAMIEN	TITLE_	Qui e to ve de crea ces	DATE	

•

r	ONDIT	ONE	0.5	PAON	 1E	ANYI