

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>5. State Oil & Gas Lease No.</p>
<p>2. Name of Operator BTA OIL PRODUCERS</p>		<p>7. Unit Agreement Name</p>
<p>3. Address of Operator 104 South Pecos</p>		<p>8. Farm or Lease Name Penn, 7504 JV-D</p>
<p>4. Location of Well UNIT LETTER "H", 1880 FEET FROM THE North LINE AND 560 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 12-S RANGE 33-E NMPM.</p>		<p>9. Well No. 2</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4283' GL</p>		<p>10. Field and Pool, or Wildcat Bagley, North (Penn)</p>
<p>12. County Lea</p>		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-11-75 - Circulated for DST #1. POH. Picking up test tool.

9-12-75 - Non-Commercial show - Dry hole.

Present Conditions

TD - 10,500' Pg - 3625'

Casing - 12-3/4" @ 380' w/400sx circ., 8-5/8" 24# K-55 STC @ 3725' w/450sx T/c 2520'

Plugging Procedure

1. Cut & Rec 8-5/8" csg. T/C @2520'.
2. Set 65 sx cmt @ 8-5/8" stub.
3. Set 65 sx cmt @ 380'.
4. Set 10 sx cmt @ surface.
5. Install Dry hole Marker.

mud between all plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bob Newland Bob Newland TITLE Regulatory Supervisor DATE 9/16/75

APPROVED BY John W. Runyan TITLE Geologist DATE 9/16/75
CONDITIONS OF APPROVAL, IF ANY: