

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
1625 N. French Dr.
Hobbs, NM 88240
FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT -" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. LC 065151
2. Name of Operator Dugan Production Corp.	6. If Indian, Allotted or Tribe Name
3. Address and Telephone No. P.O. Box 420, Farmington, NM 87499 (505) 325 - 1821	7. If Unit or CA, Agreement Designation
Location of Well (Footage, Sec., T., R., M., or Survey Description) 800' FEL & 800' FSL (Unit P) SE/4 SE/4, Sec. 23, T9S, R37E, NMPM	8. Well Name and No. Bilbrey 23 #6
	9. API Well No. 30 025 25296
	10. Field and Pool, or Exploratory Area Sawyer, West (San Andres)
	11. County or Parish, State Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to plug well as follows:

1. Set cast iron bridge plug @ 50' above perforations and spot 35' cement on top of plug.
2. Spot plug 4135'-4235' inside casing.
3. Perforate 50' below base of salt @ 3000'. Squeeze 100' plug outside casing and leave plug inside casing @ 2815'.
4. Spot 100' plug @ top of salt 2250'-2350', inside casing.
5. Spot 100' plug @ surface casing, 300'-400'.
6. Spot 50' surface plug.
7. Cut off wellhead. Install dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed John Alexander Title Vice-president Date 01/19/2000

(This space for Federal or State office use)

Approved by (ORIG. SGD.) DAVID R. GLASS

PETROLEUM ENGINEER

JAN 28 2000

Approved by _____ Title _____ Date _____

Conditions of approval, if any:

SEE ATTACHED FOR

Title 18 U.S.C. Section 1001 makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within the jurisdiction of such department or agency.

*See Instruction on Reverse Side

IC GWW

