

NEW MEXICO OIL CONSERVATION COMMISSION

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

| | |
|--------------------------------|---|
| 5a. Indicate Type of Lease | |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator SKELTON OIL COMPANY | 8. Farm or Lease Name BOBBIE |
| 3. Address of Operator P.O. BOX 840 HOBBS, NEW MEXICO 88240 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER J 1980 FEET FROM THE SOUTH LINE AND 1830 FEET FROM THE EAST LINE, SECTION 26 TOWNSHIP 11 S RANGE 37 E NMPM. | 10. Field and Pool, or Wildcat |
| 15. Elevation (Show whether DE, RT, GR, etc.) 3920' GR | 12. County LEA |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLUGGED & ABANDONED 10-29-77

Put 200' cement plug from 5150 to 4950'
tagged cement @ 4900'
Jet cut casing @ 3823'
Pulled & layed down 3823' of casing
Put 100' plug in & out of 5 1/2 casing stub @ 3823'
Tagged cement @ 3715'
Put 100' Cement plug @ 1600 to 1500' at top of salt
Tagged cement @ 1460'
Put 15 sxs plug @ surface
Installed dry hole marker
Cleaned up location for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED George Fisher TITLE Office Mgr DATE 1-23-78

APPROVED BY M. J. Crossland TITLE OIL & GAS COMMISSIONER DATE JAN 25 1978

CONDITIONS OF APPROVAL, IF ANY: