

DISTRICT I  
P.O. Box 1930, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-25374
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 1349 G

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>7. Lease Name or Unit Agreement Name  Tenneco Sunshine</p>	
<p>1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		<p>8. Well No. #2</p>	
<p>2. Name of Operator Danny R. Watson Operator</p>		<p>9. Pool name or Wildcat North Bagely Permo Penn</p>	
<p>3. Address of Operator P.O. Box 8 Tatum, N1 88267</p>			
<p>4. Well Location Unit Letter <u>P</u> : <u>810</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>1</u> Township <u>12S</u> Range <u>32E</u> NMPM Lea County</p>			
<p>10. Elevation (Show whether DF, RKB, RT, GR, etc.)</p>			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-2 thru 7-5-90  
Pigged up pulling unit pulled tubing and put in work string  
Acidized with 4000 gal N.E.F.E. acid 80 ballsealers showed good action.  
Acidized zones 9614-22 9990-10,000 10,051-55 10,100-10,110

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Danny R. Watson TITLE Operator DATE 8-7-90

TYPE OR PRINT NAME Danny Watson TELEPHONE NO. 398-3490

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: