

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
POST OFFICE BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS)		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
		5. State Oil & Gas Lease No.	
1. OIL GAS WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name	
2. Name of Operator Read & Stevens, Inc.		8. Farm or Lease Name Fawn Cherie	
3. Address of Operator Post Office Box 1518, Roswell, New Mexico 88202-1518		9. Well No. 1	
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE. SECTION 26 TOWNSHIP 10S RANGE 36E NMPM		10. Field and Pool, or Wildcat Dickenson San Andres	
5. Elevation (Show whether DF, RT, GR, etc.) 4004' RKB		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-04-86 RU unit, pull rods & tbq.

10-05-86 Spot 25sx class "C" cmt 5000' to 4900'.

11-06-86 Tag plug @ 4967', spot 20sx cmt 4967'-4867', wait 4 hrs, tagged plug @ 4873', spot 25sx 4208' -4108', circ hole w/Brine mud, perf 4 holes 2322', pmp 100 sx class "C" cmt @ 1500psi, SDON.

11-07-86 Unseat pkr, tag plug @ 2076', PU tbq, run free pt, csg was not free, perf csg @ 370', set pkr @ 188', squeeze w/70sx class "C" cmt, displace to 260', SDON.

11-10-86 POH w/pkr, spot 10sx class "C" cmt @ surface, cut off csg head, cut off anchors, prep to clean loc.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. J. Stohls TITLE Drilling and Production Manager DATE November 18, 1986

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE JAN 26 1987

CONDITIONS OF APPROVAL, IF ANY: