

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

RECEIVED FEB - 9 1998  
Form 6103  
Revised 4-1-89

**DISTRICT I**

P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO. 30-025-25846
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-3861
7. Lease Name or Unit Agreement Name New Mexico State Com.
8. Well No. 1
9. Pool name or Wildcat Mes Calero (Morrow)

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Santa Fe Exploration Company	
3. Address of Operator 201 W. 3rd, Rosewell, NM 88201	
4. Well Location Unit Letter <u>M</u> : <u>860</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>19</u> Township <u>10 South</u> Range <u>32 East</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4381 GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-27-98 1) Set 5 1/2" CIBP @ 4102.
- 1-27-98 2) Circulate hole w/10# brine w/25lb salt gel per bbl.
- 1-27-98 3) Spot 25 sx plug on top of CIBP @ 4102'
- 1-28-98 4) Cut 5 1/2" csg @ 3114' Lay down csg
- 1-28-98 5) Spot 25 sx plug form 3600-3500 (85/8" shoe)
- 1-28-98 6) Spot 45 sx plug @ 3165 WOC
- 1-29-98 7) TAG TOC @ 3005
- 1-29-98 8) Perf 8 5/8" Csg @ 415 Press up to 1000 psi Could not establish rate
- 1-29-98 9) Spot 65 sx plug 465-265
- 1-29-98 10) Spot 10 sx plug 30-surf
- 1-29-98 11) Cut off WH & install dry hole marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy Caruth TITLE Supervisor DATE 1-29-98

TYPE OR PRINT NAME BILLY CARUTH TELEPHONE NO. 915/523-5786

(This space for State Use)

APPROVED BY Billy E. Caruth TITLE Supervisor DATE 1-29-98

CONDITIONS OF APPROVAL, IF ANY: