

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P.O. Box 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Read & Stevens, Inc.	8. Farm or Lease Name Santa Fe
3. Address of Operator P.O. Box 1518, Roswell, NM 88201	9. Well No. 5
4. Location of Well  UNIT LETTER <u>C</u> . <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE. SECTION <u>35</u> TOWNSHIP <u>10S</u> RANGE <u>36E</u> NMPM	10. Field and Pool, or Wildcat Dickenson San Andres
5. Elevation(Show whether DF,RT,GR,etc.) 3981.3' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-6-84 Perf 4 holes @ 3700', pumped 200sx Class "C" cmt @ 1400psi, cmt displaced to 1400', cut tbq off @ 1000', circ hole w/ salt gel mud, pumped 25sx plug, 900' to 1000', pulled tbq, pumped 10sx surface plug, set dry hole marker.

7-9-84 Moved pumping unit off loc, picked up flowline, clean loc, prep for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Stubbs TITLE Drilling & Production Manager DATE 7-9-84

APPROVED BY Ronald M. Cartwright OIL & GAS INSPECTOR DATE OCT 24 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 11 1984

O.C.D.  
HOBBS OFFICE