

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-6428	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator M. C. & Dale Gandy		8. Farm or Lease Name Wiser State
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, NM 88240		9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM West 18 TOWNSHIP 10S RANGE 37E NMPM.		10. Field and Pool, or Whdcat E. Crossroads-SA
15. Elevation (Show whether DF, RT, GR, etc.) 3975 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPMS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	Squeeze & reperforate <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work began 4/16/81. Pull rods & tubing. Tag TD @ 4968.
Set RTTS Tool @ 4930 & squeeze perfs 4938-45 with 135
sacks. Drilled out cement to 4968. Perf 4958, 59 &
4960 with 3 holes. Set RTTS @ 4950 & treat with 1,000
gallons 20% regular acid. Swab 40 bbls load. Run tubing,
rods & pump. 4/29/81 pump 1 bbl oil & 200 bbls water per
day.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>Thomas N. Hall</i></u>	TITLE Agent	DATE 5/12/81
ORIG. SIGNED BY Jerry Sexton	TITLE	DATE
APPROVED BY <u><i>Don A. Shaw</i></u>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		