UNITED STATES DEPARTMENT OF THE INTERIOR

			orm Approved. udget Bureau No. 42–R1424				
-	5. LEASE						
1	LCO_63623-	Α					
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME						
ᅱ							
١	7. UNIT AGREEME	NT NAM	ΛE				
t							
_]	8. FARM OR LEASE						
1	Dome Wickso	n Et	Al,	<u>Fede</u>	ral :	5	
	9. WELL NO	÷	/\				
1	1 ===	<u> </u>	•		· 		
_	10. FIELD OR WILDO	CAT NA	ΜĒ				
-	Wildcat -				<u>:</u>		
	11. SEC., T., R., M.,	OR BL	K. AN	ID SUF	VEY (OR	
7	AREA	C. D		- 1			
-	Sec 5, T-10						
	12. COUNTY OR PA	RISH					
	Lea		We	w Me.	XICO		
_	14. API NO.	•	Ĭ.				
,	15. ELEVATIONS (S	HOW F)E #	DD A		(D)	
	3920.3 G		лг, n	υ ιο, Αι	אַ עאַ נ	U)	
	3920.3 u	<u> </u>		1 1		_	
		- 1					
1	VEM.		•-				
]	V IS III.						
	(NOTE Report results	of mult rm 933	iple co 0.)	mpletic	n or ze	one	
	1980 change on Fo		,		:		
		-		: :		÷	
A	IL SURVEY						
1	MEXICO				7		
atı	e all pertinent details,	and g	ive p	ertiner	t dat	es.	
d	lirectionally drilled, giv	e subsi	rface	locati	ons a	nd	
en	nt to this work.)*				-		
			-	<u>.</u> .	į		
.1	foot (5 sy) com	+					
7	тыыт гү сүн сем	ωn T					

GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a difference reservoir. Use Form 9-331-C for such proposals.) gas well 💢 other well 2. NAME OF OPERATOR Dome Oils, Inc. 3. ADDRESS OF OPERATOR 290 One Marienfeld Place Midland, Texas 79701 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES U. S. GEOLOGIC ABANDON* (other) HOBBS, NEW 17. DESCRIBE PROPOSED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones perting Pull rods & tubing. Set CIBP at 4950'. Top with 35 lineal feet (5 sx) cement. Run free point indicator. Pull 4 1/2" casing estimated to be 1500'+. Spot 100' Class "C" cement (25 sx): 50' inside casing stub and 50' above stub. Spot 100' Class "C" cement (40 sx): 50' outside 8 5/8" casing and 50' inside bottom of 8 5/8 @ 426'. Spot 10 sx cement at surface. 7. Clean location as per USGS requirements.

Company of the second

RECEIVED

and the state of the state of

DEC 23 1380

OIL CUNSERVATION DIV