STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

48. 07 COPIES MECEIVED		
_ DISTRIBUTION		
SANTA FE	T	
FILE	I	
U.S.G.S.	T	
LAND OFFICE	T	
DPERATOR	7	

OIL CONSERVATION DIVISION

_ DISTRIB	UTION	P. O. BOX 2088			-	Form C-103 - Revised 10-1-78	
SANTA FE		SANTA F	E, NEW	MEXICO 875	01		•
FILE		4				5a. Indicate Type	of Lease
U.S.G.S.		4				State	Fee X
LAND OFF	C &	-l ·				5, State Oil & Go	
OPERATOR		ك				5, 5,5,5,6 0 0	20400 1101
						tumm	mmm
	SUNDE	RY NOTICES AND REPO	RTS ON	WELLS		///////////////////////////////////////	
(DO NOT U	PR THIS FORM FOR PR "APPLICA" I BU	TION FOR PERMIT -" (FORM C-10	I) FOR SUC	CK TO A DIFFERENT PROPOSALS.)	RESERVOIR.	_((((((((((((((((((((((((((((((((((((((
١.						7. Unit Agreemen	it Name
OIL X	GAB WELL	OTHER-					
2. Name of Operato						8. Farm or Lease	Name
							•
	l 0il & Gas (Corporation				Santa Fe	<u> </u>
3. Address of Oper	ator					9. Well No.	
P. O. 1	Box 235, Mid	land, Texas 79702				5	
4. Location of Wel	1					10, Field and Po	ol, or Wildcat
	Δ	660	Morth		660	West Sawver	(San Andres)
UNIT LETTER _		660 FEET FROM THE	NOTEN	LINE AND	TEET FRO	minimin "	TITITITITI
THE East	LINE, SECT	10H 33 TOWNSHIP	<u>9-S</u>	RANGE	37-E NMPN	· ////////	
						VIIIIII	7//////////////////////////////////////
		15. Elevation (Sho	w whether	DF, RT, GR, etc.)		12. County	
		3969' GL	3985	¹ KB		Lea	
7777777	<i></i>						
	Check	Appropriate Box To In-	dicate N	ature of Notice	e, Report or O	ther Data	
	NOTICE OF I	NTENTION TO:			SUBSEQUEN	IT REPORT OF:	
PERFORM REMEDIA		PLUG AND ABA	NDON [REMEDIAL WORK		ALTER	ING CASING
	一	, 200 And Aba	<u>-</u>		H		=
TEMPORARILY ABAN	HOOH			COMMENCE DRILLI		PLUG /	AND ABANDONMENT
PULL OR ALTER CA	BING	CHANGE PLANS	اليا '	CASING TEST AND			<u></u>
				OTHER COM	pietion		[X]
OTHER							
				·			
17. Describe Property work) SEE RU		Operations (Clearly state all pe	rtinent dett	ils, and give pertin	ient dates, includin	ig estimated date of	starting any proposed
work) see no	LE 1103.			•			
Comp	letion Report	r:					
<u> </u>		- -					
_ 11 1	01 D-211-3	1					
.1.1-1-	-or printed	d cement to 5011'			•		•
11-2-	-81 PBTD 50	Oll' Set frac ring	@ 4989	' tested ca	asing to 150	00# held OK	
		-					
11-3-	-81 Ran GR-	-N/CB Logs					
	or non on	n, ob bogo					
17 /	01 D	/0/21 501 /0/71					
11-4-	-or rerra	4943'-59', 4967'-	500/ T	ith I spi w	ith casing g	gun.	
11-5-	-81 Ran pki	r on 2 3/8" tbg. to	4890'.	Treat with	n 19,500 gal	. acid in	
•		es with 1,100# salt					
	Ü	•		5 5 7 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
11-6-	.21 Prop to	o swab test.	100 mg (100 mg) 100 mg (100 mg)				
11-0-	or treb re	swau Lest.					
				and the second			
				ga i s			
		•	11.				
	what the info-	on above is true and complete to	the best	f my knowledge co	t belief		
Ib. I hereby certif	y that the informatio	" nove is true and complete to	the nest (· *** Juonteage auc			
1	///	4					
To	66m	Tiphenson.	itLE F	roduction Ar	nalvst	DATE 12	-2-81
	The transfer of the seq						- 19 19 19 19 19 19 19 19 19 19 19 19 19 19 19