

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Re-Entry	7. Unit Agreement Name ---
2. Name of Operator Challenger Minerals Inc.	8. Farm or Lease Name Bowman et al
3. Address of Operator 12707 N. Freeway, Suite 500, Houston, TX 77060	9. Well No. 1
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660' FEET FROM THE East LINE, SECTION 12 TOWNSHIP 9S RANGE 34E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4210.3 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Temporarily Abandon <input checked="" type="checkbox"/>

** Verbal Approval by Mr. Jack Griffin w/ NM Oil Conservation Div. @ 1830 HR 12/6/87.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RE-ENTRY of Adams Exploration Co., Bowman et al No. 1, which was P&A'd in 1981. Begin operations 11/18/87. Dig out casing stubs. Install & Test 10", 3M x 8 5/8" SOW casing head. Install and test BOPE. Clean out cement plugs and open hole to top of 5 1/2" casing at 6910'. Mill & Dress 5 1/2" casing from 6910' to 6936'. Attempt w/o success to tie-back the 5 1/2" casing to the surface. The 5 1/2" casing left in well is from 6936' to 9899'. Ran drill pipe open-ended to 6986'. Hole is filled w/ 10.3 ppg, 33 sec. viscosity salt gel mud. Spot 60 sxs Class "C" Cement @ 6986'. WOC. Tag Top of cement @ 6841'. Cement plug #1 @ 6841' to 6986'. POOH to 5412'. Spot 35 sxs Class "C" cement. Cement plug #2 at 5312' to 5412'. POOH to 3938'. Spot 50 sxs Class "C" cement w/ 2% CaCl2. WOC overnight. Tag top of cement @ 3752'. Cement plug #3 @ 3752' to 3938'. Base of 8 5/8" casing is at 3887'. POOH to 2338'. Spot 35 sxs Class "C" cement. Cement plug #4 @ 2238' to 2338'. POOH & LD Drill Pipe. Bolt 1/2" steel plate over wellhead. Nail 3" x 12" Boards over cellar. Well temporarily abandoned on 12/8/87. RD & MO equipment. Witnessed by Mr. R. A. Sadler w/ New Mexico Oil Conservation Division. Well was Temporarily Abandoned pending further work in early 1988.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>W. C. Young, III</i>	TITLE Vice President	DATE 12/14/87
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR		
APPROVED BY	TITLE	DATE DEC 17 1987
CONDITIONS OF APPROVAL, IF ANY:		

TA expires 6-1-88

RECEIVED

DEC 16 1981

OCD
HOBBS OFFICE