NO. OF COPIES ACCEIVES	JIL CONSERVATION DIVISION	
DISTRIBUTION		Form C-103
SANTA FE	P. O. BOX 2088	Revised 10-1-78
FILE	SANTA FE, NEW MEXICO 87501	· · · · · · · · · · · · · · · · · · ·
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5. State Otl & Gas Lease No.
	·	
SUNDRY 100 NOT USE THIS FORM FOR PROP USE "APPLICATION		
I. OIL GAS .	OTHER- Dry Hole	7, Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name	
Adams Exploration Compa	Bowman etal	
3. Address of Operator	9. Well No.	
P. O. Box 10585	1	
4. Location of Well	10. Field and Pool, or Wildcat	
H 1980 FEET FROM THE NOTTH LINE AND 660 FEET FROM THE		Vada (Penn)
East LINE, SECTION	NMPM. ()	
	15. Elevation (Show whether DF, RT, GR, etc.)	ΔΗΠΗΠΗΠΗΠΗ
	12. County	
	4210.3 GR	Lea
16. Check A	ppropriate Box To Indicate Nature of Notice, Repor	t or Other Data
NOTICE OF IN	EQUENT REPORT OF:	
	PLUG AND ABANDON REMEDIAL WORK	
PERFORM REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
		·
0THER		

On 1-12-81, ran 5 1/2" Halliburton EZSV cement retainer. Set retainer on wireline at 9779'. Ran tubing and stung into retainer. Halliburton squeezed Bough C perforations 9791, 92, 93, 94, 95, 96, 97, 98, 99, 9800, 01, 02, 03, 04, 05, 06, 07, 08, 09, 10 (20 holes) with 200 sxs. Class "H" with 4/10% Halad 22 A & 1/2# flocele per sx. Squeezed to 3500 psi. Pulled out of retainer and reversed out 140 sx. cement to pit. Perforated Bough C formation with one JSPF at 9738, 39, 40, 49, 50, 51, 52, 62, 63, 64 (10 holes). Ran packer and set at 9704'. Acidized with 600 gals. 15% NEFE acid. Swabbed back load water and had no additional fluid entry. Halliburton squeezed Bough C perforations 9738'-9764' with 75 sxs. Class "H" with 4/10% Halad 22 A & 1/2# flocele per sx. Squeezed to 4500 psi. Released packer at 9704' and reversed out 37 sxs. cement to pit. Ran 300 joints open ended tubing to 9300'. Rigged down pulling unit. Moved in and rigged up casing pulling unit on 2-11-81. Ran tubing and tagged top of cement at 9636'. Mixed 85 sxs. gel and circulated hole with mud. Pulled tubing out of hole. Welded nipple on 5 1/2" casing. Ran free point indicator and shot off casing at 6910'. Pulled and laid down 157 joints 5 1/2" casing 6910'. 5 1/2" casing left in well is from 6910' to 9899'. Ran open ended tubing to 6960'. Displaced hole with mud. Spotted 35 sxs. Class "C" cement plug at 6960'. Pulled tubing and let cement set overnite. Ran tubing and tagged TOC at 6905'. Spotted 60 sxs. Class "C" Cement plug at 6905'. Pulled tubing and let cement set overnite. Ran tubing and tagged TOC at 6770'. Pulled bottom of tubing to 5410' (Continued on attached sheet)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
Sturl Dougassteve A. Douglas	TITLE_	Division Engineer	DATE <u>4-12-82</u>		
APPADVED AV / - A tustom in	TITLE_	OIL & GAS INSPECTOR	DATE MAY 25 1982		
CONDITIONS OF APPROVAL, IF ANYI					

RECEIVED

APR 1 3 1982

©.⊂.0. HO≳85 OFFICE