Submit 3 Copies to Appropriate	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89
District Office DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30-025-27180
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lesse No. PUN 18451
	OFF AND DEPORTS ON WELL	<u> </u>	
(DO NOT USE THIS FORM FOR PRI DIFFERENT RESE (FORM C	ICES AND REPORTS ON WELL OPOSALS TO DRILL OR TO DEEPEN (RVOIR USE "APPUCATION FOR PER :-101) FOR SUCH PROPOSALS)	CH PLUG BACK TO A	7. Lease Name or Unit Agreement Name Sawyer
1. Type of Well: OIL WELL X GAS WELL	OTHER		8. Weil No.
2. Name of Operator			a. Well No.
Baxter, Kelly H.			9. Pool name or Wildcat
3. Address of Operator			Crossroads Siluro. Dev.
P. O. Box 11193, Mid	land, 1X /9/UZ		
4. Well Location Unit Letter K: 1650 Feet From The South Line and 2310 Feet From The West Line			
27 9S Range 36E NMPM Lea County			
Section 2 Townsmip 10 Elevation (Show whether DF, RKB, RT, GR, etc.) 4041' KB			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND CEMENT JOB		CEMENT JOB	
OTHER: Well Plugged and	d Abandoned 🔀	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all perturent details, and give perturent dates, including estimated date of starting any proposed work) SEE RULE 1103. Move in Pig. up. Install BOP. Pick up and Tally 2 3/8" Tubing in Hole to 4589;			
Circulate Mud, Spot 50 sacks of Cement, Pull Tubing up hole. Tagged cement at 4431', good plug from 4589-4431 pulled tubing to 4200' spotted 50 sacks of cement, pulled tubing up hole, waited on cement, tagged cement at 4074, plug from 4200-4074, pulled tubing to 1800', spot 35 sacks of cement from 1800-1650, pulled tubing to 50' from surface, circulated 15 sacks of cement to surface, cut off wellhead, installed marker. Moved off location.			

TYPE OR FRANT NAME

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

I hereby certify this the information above is true and complete to the best of my knowledge and belief.

Agent

Agent

Agent

Agent

Agent

Agent

Date

2/23/93

TITLE

Agent

TITLE

Date

Date

CONDITIONS OF APPROVAL, IF ANY: