

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
LG-0629

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
1. Name of Operator <u>TXO Production Corp.</u>	8. Farm or Lease Name <u>Inbe State</u>
2. Address of Operator <u>900 Wilco Bldg., Midland, TX 79701</u>	9. Well No. <u>1</u>
3. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>14</u> TOWNSHIP <u>11N</u> RANGE <u>33E</u> NMPM.	10. Field and Pool, or Wildcat <u>Inbe/Permo (Penn)</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4231' GR</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging procedure as follows:

1. Set CIBP @ 9400 and cap with 35' cmt.
2. Cut and pull approximately 7520' of 5 1/2" csg.
3. Spot 35 sx in and out of 5 1/2" csg. stub.
4. Set plugs as follows:
 - A. 50 sx from 6650 to 6750'
 - B. 50 sx from 5200 to 5300'
 - C. 50 sx from 3750 to 3850'
 - D. 50 sx from 850 to 950'
 - E. 10 sx at surface

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Clark Vinton TITLE Production Engineer DATE 5-5-82

ORIGINAL SIGNED BY
APPROVED BY JERRY SEXTON TITLE _____ DATE MAY 10 1982
CONDITIONS OF APPROVAL _____

RECEIVED

MAY 8 1982

CLC
HOBBS OFFICE