

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-0269	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas Oil & Gas Corp.	8. Farm or Lease Name Inbe State
3. Address of Operator 900 Wilco Bldg., Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> , <u>660</u> FEET FROM THE <u>north</u> LINE AND <u>1980</u> FEET FROM THE <u>east</u> LINE, SECTION <u>14</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> NMPM.	10. Field <u>Inbe</u> Pool, on Wildcat Inbe/Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4230.8 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Operations report</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 15" conductor pipe on April 21, 1981. Installed legal lease sign @ well site.
5-18-81 MIRT, prep to spud 14 3/4" surface hole on 5-19-81.

1. Drill 14 3/4" hole to 375' w/FW spd mud & set 11 3/4" 42# H-40 ST&C csg. Cmt to surf.
2. Drill out with 11" bit using FW. Drill to approx 3800' & set 2200' 8 5/8" 24# K-55 & 1600' 8 5/8" 28# S-80 ST&C csg. Cmt to surface.
3. Drill out with 7 7/8" bit & water. Drill to Wolfcamp at approx 8500'. Bring weight up to 9.8# using brine water.
4. Drill to Penn at approx 9450'. Mud up with salt gel and drispac for 10#, 35-45 Vis, 5 cc WL. Drill to TD of 10,400'.
5. Run OH logs and caliper.
6. DST as required.
7. Run 4 1/2" 10.5 and 11.6# K-55 ST&C csg and complete through perforations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.M. Mayfield (W.M. Mayfield) TITLE Drilling Foreman DATE 5-18-81

APPROVED BY Jerry S. TITLE Drilling Foreman DATE May 25 1981

CONDITIONS OF APPROVAL, IF ANY: Dist 1, 8, 10