-STATE OF NEV		I	· –	-		
ENERGY AND MINERAL		OIL CONSERV	ATION DIVISION	1		
AR. OF COPIES RECEN	<u>───</u> ┤──┤──┤	OIL CONSERVATION DIVISION				Form C-103
DISTRIBUTIO		P. O. BOX 2088 SANTA FE, NEW MEXICO 87501				Revised 10-1-78
FILE	<b>}</b> ┥	SANTA FE, NE	W MEXICO 87501	,		
V.S.G.S.					5a. Indicate Type	
LAND OFFICE					State X	F 00
OPERATOR					5. State Oll & Ga	
·····					L-527	4
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR FEMILE -" (FORM C-101) FOR SUCH PROPOSALS.)						
···					7. Unit Agreemen	t Name
					8. Farm or Lease	Name
The T	ovolody Tra					
Ike Lovelady, Inc.						
P.O. Drawer 2666, Midland, Texas 79702					1	
4. Location of Well					10, Field and Po	ol, or Wildcat
1	660	South	1980	_ FEET FROM	W. Sawver	, San Anders
UNIT LETTER N	,,	FEET FROM THE	LINE AND	_ /LLT /ROM	innin in the second	innnnn i
THE West	LINE, SECTION	16 TOWNSHIP9-	-S RANGE 37-E	NMPM.		
mmm	mmm	15. Elevation (Show wheth	her DF. RT. GR. etc.)		12. County	XIIIIIII
		3992 GR			Lea	
it.	Check Appror	oriate Box To Indicate	Nature of Notice, Rep	port or Oth	er Data	
	DTICE OF INTENT				REPORT OF:	
PERFORM REMEDIAL WOR	к [] .	PLUG AND ABANDON	REMEDIAL WORK		- ALTER	
TEMPORARILY ABANDON	П		COMMENCE DRILLING OPHS.		PLUG A	ND ABANDONMENT
FULL OR ALTER CASING	A	CHANGE PLANS	CASING TEST AND CEMENT	X ept		
			OTHER update or		ion	X
OTHER				L		
work; SEE RULE 1	103.		details, and give pertinent dat			
Drilled 7 7	1/8" hole to 52	250'. Ran Welex CD	NL & Guard logs. F	Ran new 4	1/2" 10.5#	casing w/
Guideshoe, Latch	1 down baffle,	& two stage collar	r. Cemented 4 1/2"	'@ 5250'	w/ baffle	(PBTD) @ 5209
& DV Tool @ 2349	)' (Top of salt	z @ 2304 <b>')</b>				
Cemented th	rough shoe w/	660 sx. 50/50 Cla	ss "C" Posmix W/ 8#	f salt/sk	, ¼# Flocel	e/sk., & .5%
CFR-2. Circulat	ed through DV	tool 6 hrs & cemen	nted 2349 to surfac	ce w/ 700	sk Hallibu	rton Lite w/
15# salt & ½ # E	locele per sac	ck. Circulated ou	t 109 sk. Job comp	plete at	12:15 A.M.	2-18-81.

- Released Drilling rig.
- 2-23-81 RIH W/ bit & 2 3/8" tubing to DV tool. Tested casing 2349' to surface w/ 2000#. Drilled DV tool & RIH w/ bit to 5209'. (PBTD) Test casing 5209 to surface w/ 2000# for 1/2 hr. Test O.K. Displaced casing w/ KCL water & POH.
- 2-24-81 Ran GRN & perforated 2 Js/ft 5023'-5030'. Acidized w/ 500 gals 15% NEA. Swabbed back load water & 7 B blackwater w/trace oil, no gas.
- 2-27-81 Set CIBP @ 5010' & perforated 2 Js/ft. 4917'-23', 4933'-38', 4947'-52', 4960'-63', & 4972'-79'. Acidized perfs w/ 6000 gals 20% NEA. Swabbed back LW & new water cut 10-15% oil at 6 B/hr.
- 3-4-81 Set CIBP @ 4967' to shut off perfs 4972'-79'. Tested remaining perfs 4917'-63'. Swabbed 10 B fluid/hr. Formation water cut 10-15% oil. Reacidize perfs 4917'-63' w/ 8000 gals 20 NEA. Used 550# rock salt & 500# Benzoic Acid Flakes to divert acid. (con't on next page)

18. I hereby certify that the information above is true and complete sickto N, Nam,	to the best of my knowledge and belief.	March 10,1981
APPROVID BY	TITLE	M

CONDITIONS OF APPROVAL, IF ANY:

3-4-81 (con't)

.

Swabbed back load water & tested well at 9 BW/hr. w/ 10% oil. 3-10-81 POH w/ test packer & RIH w/ tubing for pumping. Prep to set pumping unit.

**.** .

.