

RICT I
Box 1980, Hobbs, NM 88240
RICT II
O. Drawer DD, Artesia, NM 88210
RICT III
000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-27349 ✓	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. VA-172	
7. Lease Name or Unit Agreement Name Mission AMV State	
8. Well No. 1	
9. Pool name or Wildcat Vada Penn.	

Unit Letter	K	:	2086	Feet From The	South	Line and	1874	Feet From The	West	Line
Section	30	Township	10S	Range	34E	NMPM	Lea	County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4231.4' GR										

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER RE-ENTRY
Name of Operator YATES PETROLEUM CORPORATION
Address of Operator 105 South 4th St., Artesia, NM 88210
Well Location

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:
Cut and pull 5½" pipe at 7100'. Set cement plugs as follows:
Plug #1 9800' with 35 sx cement, tag plug (or CIBP + 35' cement w/no tag)
Plug #2 9000' with 35 sx cement, tag plug (or CIBP + 35' cement w/No tag)
Plug #3 7200-7000' with 35 sx cement, stub plug, tag
Plug #4 5500' with 35 sx or 100'
Plug #5 4040-3940' with 50 sx cement
Plug #6 2250-2150' with 35 sx cement
Plug #7 10 sx surface plug.

Plugging procedure approved by Paul Kautz, NMOCD, Hobbs, NM, 4-28-93.
NOTIFY NMOCD, HOBBS, NM, 24 HOURS IN ADVANCE OF PLUGGING. (505/393-6161)
USE 25#/BBL SALT GEL BETWEEN PLUGS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-29-93
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL MONITOR BY JERRY SEXTON
SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MAY 03 1993