	 1				Form C-103	
N). OF COPIES RECEIVED					Supersedes O	
DISTRIBUTION	NEW MEXICO OIL CONSERVATION COMMISSION			ОN	C-102 and C- Effective 1-1-	
SANTA FE		HER MEXICO OIL CONS	EKTATION COMMISSION			
FILE			-		Sa. Indicate Type	of Lease
U.S.G.S.					State XX	Fee
OPERATOR	+-+-				5. State Oil & Go L-6444	is Lease No.
		·····			mm	mmm
(DO NOT USE THIS	SUNDRY NOTICE FORM FOR PROPOSALS TO DE SE "APPLICATION FOR PERM	S AND REPORTS ON PLUG BATT -" (FORM C-101) FOR SUC	WELLS BACK TO A DIFFERENT RESERVED PROPOSALS.	IVOIR.	7. Unit Agreeme	nt Name
WELL A	AS OTHER+				8. Farm or Leas	
Name of Operator						
Brazos Petroleum Company					Bass State	
. Address of Operator	200 Willowd To	exas 79702			1	
	782 - Midland, Te	EXAS /9/02			10. Field and Pa	ool, or Wildcat
. Location of Well	1980	EET FROM THE North	2030	FFFT FROM	East Cros	sroads
•		TOWNSHIP 10-S			KEAN ANDRO	
		15. Elevation (Show whether			12. County	,44444
	//////////////////////////////////////	3682.7 GF			Lea	
	7111111111X	te Box To Indicate I		0.1		
NO	TICE OF INTENTION		S REMEDIAL WORK	UBSEQUENT	REPORT OF	RING CASING
TEMPORARILY ABANDON		[]	COMMENCE DRILLING OP	7-7	PLUG	AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	OTHER XX	41 1de		[
			;			
OTHER			<u>'</u>	 :		Constitution and property
	Completed Operations (Co.	learly state all pertinent de	tails, and give pertinent o	lates, including	estimated date of	starting any propose
work) SEE RULE 11						
8-30-81	down assembly, P w/150 sx Class "	20 jts 4 1/2" 10 engo stage tool 8 C" 50:50 POZ w/8 8-29-81. Rig re	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented
8-30-81	down assembly, P w/150 sx Class "	engo stage tool 8 C" 50:50 POZ w/8a	& guide shoe. (# salt per sx. &	Csg set @ & 1/4# flo	4956 KB.	Cemented

Production Clerk

281