				·.			
Submit 3 Copies To Appropriate Distr Office	ict	State of New N	<b>Aexico</b>		Form C-103		
District I	Energy	, Minerals and Na	tural Resources	· · · · · · · · · · · · · · · · · · ·	Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 8824 District II				WELL API NO. 30-025-27569			
811 South First, Artesia, NM 88210	OIL C	CONSERVATIO			of Lease		
District III 1000 Rio Brazos Rd., Aztec, NM 874	10	2040 South Pacheco			5. Indicate Type of Lease STATE STATE SEE		
District IV		Santa Fe, NM	87505	6. State Oil & G			
2040 South Pacheco, Santa Fe, NM 87	'505			0. State of a G	as Lease 140.		
(DO NOT USE THIS FORM FOR PR DIFFERENT RESERVOIR. USE "A	OPOSALS TO DRILL	EPORTS ON WEL OR TO DEEPEN OR I ERMIT" (FORM C-101)	PLUG BACK TO A	7. Lease Name of Name: Betenbough	or Unit Agreement		
PROPOSALS.) 1. Type of Well:							
Oil Well 🖾 Gas We	ll 🗌 Other	r			-		
2. Name of Operator				8. Well No. 5			
State of New Mexico 3. Address of Operator				Dool name or Wild	Jaat		
J. Address of Operator				Pool name or Wild Bough Permo Penn			
4. Well Location							
Unit LetterL	:1980fe	et from the _South_	line and _66	0feet from	n theWestline		
Section 12	Т	ownship 9-S	Range 35-E	NMPM	Lea County		
tan ing karang ng mang ng mang Ng mang ng mang Ng mang ng mang	10. Elevat		DR, RKB, RT, GR, et		and the second sec		
11 01	4144 KB						
			Nature of Notice,	-			
PERFORM REMEDIAL WORK							
FERFORM REMEDIAL WORK		ABANDON A	REMEDIAL WOR				
TEMPORARILY ABANDON	CHANGE P	LANS	COMMENCE DR	ILLING OPNS. 🗌	PLUG AND		
PULL OR ALTER CASING		ON	CASING TEST A	ND 🗌			
OTHER:			OTHER:				
12. Describe proposed or com	pleted operations.	(Clearly state all p	ertinent details, and a	give pertinent dates, i	including estimated date		
<ul><li>of starting any proposed w or recompilation.</li><li>All well fluid will be circu</li><li>See attached plugging proc</li></ul>	ork). SEE RULE	1103. For Multiple	Completions: Attac	h wellbore diagram o	of proposed completion		
			The Commis Hours prior Plugging O To be approv	SION MUST BE NO R. TO: THE: BEGINN PERATIONS FOR TH /ED:	TIFIED 24 NNG OF HE C-103		
I hereby certify that the information	ation above is true	and complete to the	e best of my knowled	ge and belief.			
SIGNATURE		TITLE			DATE		
Type or print name				Telent			
(This space for State use)		N	REPRESENTATIVE II	STAFF MANAGER	AUG 0 6 ZUUZ		
APPPROVED BY Law	W. Win	OC FIELD			DATE		
Conditions of approval, if any							

## North Lea Joint Ventures Plugging Procedure for Betenbough # 5

- 1) Move in rig up service unit
- 2) Pull rods and pump
- 3) Nipple up BOP
- 4) Pull tubing
- 5) Run sinker bar and tag PBTD
- 6) Run gauge ring to 50 ft above top perforations 9653-9679ft
- 7) Run and set CIBP at 9600 ft
- 8) Cap CIBP with 35 ft cement buy dump bailer
- 9) Run tubing to 9550 feet displace casing with mud laden fluid
- 10) Pull tubing to 7730ft
- 11) Spot 30 sx Abo cement plug
- 12) Pull tubing to 5508ft
- 13) Spot 30 sx Glorieta cement plug
- 14) Pull tubing
- 15) Weld on pull nipple and stretch 5.5" csg
- 16) Cut and pull 5.5" csg from freepoint
- 17) TOC cement estimated between 3800-5000 feet
- 18) Run tubing to 50 feet inside of 5.5" casing stub
- 19) Spot 35 sx cement
- 20) Pull tubing and WOC
- 21) Run tubing and tag cement plug, minimum 50 feet above casing stub
- 22) Pull tubing to 2400 feet
- 23) Spot 35 sx Salt cement plug
- 24) Pull tubing to 410 feet
- 25) Spot 35 sx Surface shoe cement plug
- 26) Pull tubing and WOC
- 27) Run tubing and tag cement plug
- 28) Pull tubing to 60 feet and circulate cement to surf
- 29) Pull tubing
- 30) Cut off well heads and install PXA marker
- 31) Rig down and Move out service unit
- 32) Cut off anchors 1 feet below ground level and clean location

2040 South Pacheco, Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS   7. Lease Name or Unit Agreement     (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A   7. Lease Name or Unit Agreement     DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH   8.     PROPOSALS.)   1. Type of Well:     Oil Well   Gas Well   Other					
2. Name of Operator   8. Well No. 5     State of New Mexico   8. Well No. 5					
3. Address of Operator Pool name or Wildcat   Bough Permo Penn					
4. Well Location					
Unit Letter L : 1980 feet from the South line and 660 feet from the West line					
Section 12 Township 9-S Range 35-E NMPM Lea County					
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4144 KB					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data     NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:     PERFORM REMEDIAL WORK □ PLUG AND ABANDON ☑   REMEDIAL WORK □ ALTERING CASING □					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND					
PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT COMPLETION					
OTHER: D OTHER:					

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

All well fluid will be circulated to plastic lined pit or steel tank
See attached plugging procedure

I hereby certify that the information above is	true and complete to the best of my knowl	edge and belief.		
SIGNATURE				
Type or print name (This space for State use)	"- <u> </u>	Telephone No.		
APPPROVED BY Conditions of approval, if any:	TITLE	DATE		

#### North Lea Joint Ventures Plugging Procedure for Betenbough # 5

- 1) Move in rig up service unit
- 2) Pull rods and pump
- 3) Nipple up BOP
- 4) Pull tubing
- 5) Run sinker bar and tag PBTD
- 6) Run gauge ring to 50 ft above top perforations 9653-9679ft
- 7) Run and set CIBP at 9600 ft
- 8) Cap CIBP with 35 ft cement buy dump bailer
- 9) Run tubing to 9550 feet displace casing with mud laden fluid
- 10) Pull tubing to 7730ft
- 11) Spot 30 sx Abo cement plug
- 12) Pull tubing to 5508ft
- 13) Spot 30 sx Glorieta cement plug
- 14) Pull tubing
- 15) Weld on pull nipple and stretch 5.5" csg
- 16) Cut and pull 5.5" csg from freepoint
- 17) TOC cement estimated between 3800-5000 feet
- 18) Run tubing to 50 feet inside of 5.5" casing stub
- 19) Spot 35 sx cement
- 20) Pull tubing and WOC
- 21) Run tubing and tag cement plug, minimum 50 feet above casing stub
- 22) Pull tubing to 2400 feet
- 23) Spot 35 sx Salt cement plug
- 24) Pull tubing to 410 feet
- 25) Spot 35 sx Surface shoe cement plug
- 26) Pull tubing and WOC
- 27) Run tubing and tag cement plug
- 28) Pull tubing to 60 feet and circulate cement to surf
- 29) Pull tubing
- 30) Cut off well heads and install PXA marker
- 31) Rig down and Move out service unit
- 32) Cut off anchors 1 feet below ground level and clean location



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION DISTRICT I HOBBS 1625 N.French Drive, Hobbs, NM 88241 (505) 393-6161 FAX (505) 393-0720

Jennifer A. Salisbury CABINET SECRETARY

May 1, 2000

Underwriters Indemnity Co. 8 Greenway Plaza Suite 400 Houston,Tx 77046

#### Attention : Tahir Ajaz

RE: North Lea Joint Venture Bond # BO2521 New Mexico Properties Pruitt A #1 Unit letter G, Section 17, Township 9 South, Range 34 East Betenbough #4 Unit letter J, Section 12, Township 9 South, Range 35 East Betenbough #5 Unit letter L, Section 12, Township 9 South, Range 35 East Betenbough #2 Unit letter M, Section 12, Township 9 South, Range 35 East Betenbough #3 Unit letter P, Section 12, Township 9 South, Range 35 East

### Tahir:

Per our phone conversation, the above company is the operator of 5 wells in District 1 area of New Mexico. Correspondence has been returned as undeliverable and phone numbers that we have called have been disconnected. The above wells and associated facilities are out of compliance with New Mexico rules and regulations. Through routine inspection it has come to our attention that the facilities for the Betenbough lease also has an unlined surface impoundment that will need a closure plan submitted to the District 1 Environmental Specialist at the above address.

The following options are available regarding the future disposition of this well:

- 1. Restore the wells to production .
- 2. Set plugs, conduct mechanical integrity test, and request temporary abandoned status.
- 3. Submit a proposal to plug and abandon the wells, proceed with plugging on a timely basis after the proposal has been evaluated, amended and or approved

To avoid further action on these wells the NMOCD request that you submit a NMOCD form C-103 telling us your intent for each of your wells within 30 days of reciept of this letter. If you do not respond we will have no choice but to schedule a Show Cause Hearing. We request that you notify this office 24 hours prior to any operation in order to witness the operation, either repair or plugging and pressure test upon completion of repairs or to request TXA status.

**OIL CONSERVATION DIVISION** 

Billy Prichard Deputy Inspector, District 1



Jennifer A. Salisbury CABINET SECRETARY

May 1, 2000

North Lea Joint Venture 1624 Market Street Suite 209 Denver,Colorado 80202

RE: North Lea Joint Venture Bond # BO2521 New Mexico Properties Pruitt A #1 Unit letter G, Section 17, Township 9 South, Range 34 East Betenbough #4 Unit letter J, Section 12, Township 9 South, Range 35 East Betenbough #5 Unit letter L, Section 12, Township 9 South, Range 35 East Betenbough #2 Unit letter M, Section 12, Township 9 South, Range 35 East Betenbough #3 Unit letter P, Section 12, Township 9 South, Range 35 East

## Gentlemen:

Enclosed is a copy of the letter that was sent May1,2000 to the bonding company for the above properties.

To avoid further action on these wells the NMOCD request that you submit a NMOCD form C-103 telling us your intent for each of your wells within 30 days of reciept of this letter. If you do not respond we will have no choice but to schedule a Show Cause Hearing. We request that you notify this office 24 hours prior to any operation in order to witness the operation, either repair or plugging and pressure test upon completion of repairs or to request TXA status.

**OIL CONSERVATION DIVISION** 

Billy Prichard Deputy Inspector, District 1

CC:

Chris Williams Gary Wink Sylvia Dickey Stephen Ross

CMD : OG6IPRD	INQUIRE PRO	ONGARD DUCTION	BY POOL	/WELL		/00 14:38: OGOBEP -TQ
OGRID Identifier : Pool Identifier : API Well No : 30	25 27569 Re	eport Pe	ricd - F	'rom : 01 19		Page No: 07 2000
API Well No Property	v Name	Prodn. MM/YY	Days Prod	Productio: Gas	n Volum Oil	es We Water St

Reporting Period Total (Gas, Oil) :

F6495, $Tboxe means the first state of the second state of the$	
E0403: Inere was no prodn for the well/pool in given and	
E6485: There was no prodn for the well/pool in given prd PF01 HELP PF02 PF03 EXIT PF04 GoTo PF05 PF05 PF06 GON	
DROG DWD PF06 CON	FIRM
PF07 BKWD PF08 FWD PF09 PF10 NXTPOOL PF11 NXTOGD PF12	

Betenbough #5