

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Mission Exploration, Inc.		8. Farm or Lease Name Mission 14 State
3. Address of Operator P.O. Box 2188 Hobbs, New Mexico 88240		9. Well No. #1
4. Location of Well UNIT LETTER I, 554 FEET FROM THE East LINE AND 1986 FEET FROM THE South LINE, SECTION 14 TOWNSHIP 10S RANGE 33E NADPAC.		10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4204.0'		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1-24-82

Ran & cemented 245 jnts. of 5 1/2" casing in two stages: 1st stage: 250 sx. Class "H" w/0.4% Halad 22A, 6# KCL and 1/4# Flocele per sx. 2nd stage: 800 sx. Class "H" Poz-50/50 w/2% gel 6# gilsonite, 5# salt, and 0.3% Halad-22A. Full circulation through out job. Bumped 1st stage plug w/1600#, float held. Dropped opening bomb & opened DV tool w/1800 psi. Circulated hole six hrs. & ran 2nd stage, cut job. Pumped closing plug down & bumped same w/200 psi. FRR & WOCU.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joe T. Jamies</u>	TITLE <u>NREE, Agents for Mission Exploration, Inc.</u>	DATE <u>2/10/82</u>
ORIG. SIGNED BY <u>Joe T. Jamies</u>		
APPROVED BY <u>Joe T. Jamies</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		