

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Exxon Corporation Attn: Permits Supervisor	8. FARM OR LEASE NAME Zimmerman Federal
3. ADDRESS OF OPERATOR P.O. Box 1600, Midland TX 79702	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980'FSL & 1980'FWL of Sec. 14	10. FIELD AND POOL, OR WILDCAT Vada Penn
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) KB 4372'
12. COUNTY OR PARISH Lea	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6-3-88 Set CIBP @ 8553'. Tested csg to 500# and spotted 25 sx plug on CIBP.
Spot 25 sx @ 5230' - 5130', Spot 25 sx @ 4020' - 3920', Finished displacing hole w/ gelled brine. Cut off 5 1/2" csg @ 3215' and lay down same.
6-7-88 Displaced hole w/ 10# gelled brine. Spot 35 sx @ 3215' - 3115', Spot 30 sx @ 2450' to 2350'. Spot 30 sx 1950' - 1850'. Pumped 135 sx from 450' to surf.
6-8-88 Cut off wellhead and install dry hole marker and clean up location.

RECEIVED
JUN 17 10 45 AM '88
OCT 17 10 45 AM '88

18. I hereby certify that the foregoing is true and correct

SIGNED Stephen Johnson TITLE Administrative Specialist DATE 06-14-88

(This space for Federal or State office use)

APPROVED BY CS TITLE CS DATE 6-29-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side