STATE OF NEW MEXICO



ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE November 21, 1983

TONEY ANAYA

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88240 (505) 393-6161

Jubilee Energy Corporation

3100 North "A", Bldg. "E", Suite 103

Midland, Texas 79705

Gentlemen:

Form C-103, Report of Plugging, for your Pruitt 21 No. 1-F 21-9-34 LEASE WELL NO. UNIT S-T-R cannot be approved until a Division representative has made an inspection of the location and found-it-to-be cleared to comply with Division Rules and Regulations. Please check each item in the space provided to indicate that the work has been done.

- () 1. All pits have been filled and levelled.
- () 2. Rat hole and cellar have been filled and levelled.
- () 3. A steel-marker 4" in diameter and approximately 41-above mean ground level has been set in concrete. It must show the quarter-quarter-section or unit designation, section, township, and range numbers which have been permanently stenciled or welded on the marker.
- () 4. The location has been levelled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- () 5. The dead men and tie downs have been cut and removed.
- () 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been levelled and cleared of all junk and equipment.

The above are minimum requirements and no plugging bond will be released until all locations for plugged and abandoned wells have been inspected and Forms C-103 approved. When all of the work outlined above has been done, please notify this office by filling in the plank form below and returning this letter to us so that our representative will not have to make more than one trip to the location.

)IL CONSERVATION DIVISION

ij] & Gas Inspector

Please submit Form C-105, Well Record, two copies of a notarized tabulated list of the deviation surveys, and one copy of each log run on the well.

Lease

## ILL IN BELOW AND RETURN

certify that the above work has been done and the

e ready for your inspection and anoroval - - - -

Well No. Unit