

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

Form C-103
Revised 10-1-78

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LH-1376

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator Read & Stevens, Inc.	8. Farm or Lease Name North Mescalero
3. Address of Operator P.O. Box 1518, Roswell, NM 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> . <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE. SECTION <u>2</u> TOWNSHIP <u>10S</u> RANGE <u>32E</u> NMPM	10. Field and Pool, or Wildcat Wildcat Siluro Devonian
5. Elevation (Show whether DF, RT, GR, etc.) 4279.1' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-17-83 Trip Out w/ tubing, set CIBP @ 4050' w/ 35' cmt. GIH to 3965' circ w/ salt mud, trip out of hole w/ tubing, prep to cut csg @ 2000'.

9-18-83 Csg cut off @ 1800'. pulled 43 jts & 2 cut offs, GIH w/ tubing @ 1852', spot 70 sx Class "C" cmt.

9-20-83 Tag plug @ 1520'. Spot 35sx Class "C" cmt 450'-350'. Spot 10sx. Plug @ surface w/ Dryhole Marker.

Will notify when ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce Stohly TITLE Drilling & Production Manager DATE 9-26-83

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE MAR 25 1988

CONDITIONS OF APPROVAL, IF ANY: