

STATE OF NEW MEXICO
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-83

FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
001	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plugged & abandoned		7. Unit Agreement Name	
2. Name of Operator The Stone Petroleum Corp.		8. Farm or Lease Name State	
3. Address of Operator 505 N. Big Spring, Suite 403, Midland, Texas 79701		9. Well No. #1-23	
4. Location of Well UNIT LETTER <u>1</u> <u>330</u> FEET FROM THE <u>E</u> LINE AND <u>1980</u> FEET FROM THE <u>S</u> LINE, SECTION <u>33</u> TOWNSHIP <u>11S</u> RANGE <u>36E</u> N.M.P.M.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 4016.1 G.L.		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 13,350' Dolomite. It is proposed to plug and abandon this well in the following manner.

Casing Record:

13-3/8" set @ 400' w/420 sacks cmt.
8-5/8" set @ 4365' w/1110 sacks cmt.

- Set 100' plugs as follows: 100' cement 11,544'; 9,462'; 9,310'; 7,228'; 5,860'; 4,390'; 2,300'. Plugging orders as per Eddie Seay with State Commission.
- Remove BOP stack cut off wellhead. Release rig.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Michael E. Madala TITLE Sr. Reservoir & Operations Engineer DATE 03/08/84

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE MAR 16 1984

CONDITIONS OF APPROVAL, IF ANY: