

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28500
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	L-434

7. Lease Name or Unit Agreement Name	State "4"
--------------------------------------	-----------

8. Well No.	3
-------------	---

9. Pool name or Wildcat	Flying "M" (SA)
-------------------------	-----------------

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
------------------	---

2. Name of Operator	Coastal Oil & Gas Corporation
---------------------	-------------------------------

3. Address of Operator	P.O. Box 235, Midland, Texas 79702
------------------------	------------------------------------

4. Well Location	Unit Letter F : 1880 Feet From The North Line and 1980 Feet From The West Line Section 4 Township 10-S Range 33-E NMMPM County
------------------	---

10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4256.7 GR
--	-----------

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-14-89 Set off pumping unit. RU Plugging Unit. Start LD rods.
2-15-89 Fin LD rods, POOH with tbg. Set CIBP at 4475'. GIH with tbg. Load hole with 10 PPG mud. POOH with tbg. Pick up on 5-1/2" casing, stretch free point at 1750'.
2-16-89 Run bailer and dump 35' of cement on CIBP. TOC at 4440'. Cut 5-1/2" csg. at 1890', LD same.
2-17-89 GIH with tbg. to 1940', spot 55 sack plug. WOC and tagged at 1763' (8-5/8" set at 1854'). LD tbg. Spot 10 sack surface plug.
2-20-89 Install P&A marker, cut anchors, clean and level location. Well P&A'd 2-20-89.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE	Area Superintendent	DATE 2-21-89
TYPE OR PRINT NAME	Bobby L. Smith	TELEPHONE NO.

(This space for State Use)	OIL & GAS INSPECTOR	JUN 15 1990
APPROVED BY	JACK GRIFFIN	TITLE
CONDITIONS OF APPROVAL, IF ANY:		