

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-28828

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.
V-194

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Pinnacle UZ State

1. Type of Well:
OIL WELL ☐

GAS WELL ☐

OTHER

P&A

2. Name of Operator
YATES PETROLEUM CORPORATION

8. Well No.

1

3. Address of Operator
105 South 4th St., Artesia, NM 88210

9. Pool name or Wildcat

South Button Mesa SA

4. Well Location

Unit Letter B : 330 Feet From The North Line and 2310 Feet From The East Line

Section 8 Township 9S Range 32E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4431.2' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-5-89. TIH w/CIBP and set at 3400'. Ran log from 3400-2800' with top of cement 3312'. Perforated 4 - .46" holes at 3285'. No show oil or gas.

Verbal permission obtained from NMOCD, Hobbs, NM, 8-4-89 to P&A well.

8-8-89. Plugged well as follows: Cut casing at 3185' and pulled 76 joints 5-1/2" casing. Plug #1 3390-3130' with 50 sx Class C with 2% CaCl2. WOC 2 hrs to tag plug.

Plug 75' short, re-spotted plug w/25 sx cement at 3185'.

Plug #2 1758-1650' with 35 sx cement. WOC 2 hrs. Tag plug 1650'.

Plug #3 Surface plug with 10 sx cement. Cut off 8-5/8" wellhead. Install dry hole marker.

Note: Witnessed by NMOCD representative.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Supervisor

DATE 8-9-89

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTOR

NOV 16 1989