

400 – 420' appears can be milled & cleaned up so can continue @ 420'. POOH w/ WL camera & tbg. RIH w/ camera & tried to inspect csg from surface to 395' – too cloudy – needs to set overnite. POH w/ camera. SION.
DC: \$9450 CC: \$44,150

9-28

SICP 0. PU HRC Csg inspection camera & TIH on wireline. Wtr is clear but still solids floating – can see csg ok. Found holes in csg from 100' to 400' – pin size to baseball size. Csg parted @ 401'. POOH w/ camera. RD WL Trk. Talked w/ Midland about options. Will run concave mill w/ stabilizers above to keep mill centered in csg. Will lightly fan down over metal on csg & clean out to top of fish. Will PU tools in am. SION.
DC: \$6600 CC: \$50,750

9-29

SICP 0, PU 6-1/8" concave mill (2.75') c/o (3.94') 6-1/8" stabilizer (4.64') c/o (2.98') 6-1/8" stabilizer (4.69'), c/o (0.84'), 2- 5-3/4" dc's (62.14'), c/o (1.03') & TIH on 2-7/8" tbg. Tag up @ 407'. Work concave mill to 420', tighy spot @ 415', can rotate slightly & goes thru. Returns show metal cuttings, iron sulfide & carbonate scale. Circ clean & POOH. PU 6-1/8" shoe, 5-3/4" OS 1 jt 5-3/4" WP & TIH on 2-7/8" tbg. Tag up @ 415', rotate thru, tag up @ 420', made 5' to 425', POOH, had 2 slivers of csg & 5' tbg in shoe. TIH w/tools, Tag 425', work dwn to 443', stop making hole, POOH, recovered 15' of tbg, pin end on btm. SION.
DC: \$5,300 CC: \$56,050

9-30

SICP 0, PU 6-1/8" shoe, 5-3/4" OS, 1 jt 5-3/4" wash pipe & TIH on 2-7/8" tbg. Tag @ 446', worked to 452', stopped making hole. POOH w/2- 3' pieces tbg, open end looking up – no collar. TIH to 415', rotate, would not go thru, worked up & dwn & rotate lightly, won't go thru, possible lip or bad spot, have been able to go thru this spot by just rotate & fall thru (possibly could run tapered mill to get past w/strong mill above w/stabilizer to keep centered). RD & release all equip. RDPU
DC: \$5,700 CC: \$61,750