

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-983
7. Unit Agreement Name
8. Farm or Lease Name State "A"
9. Well No. 1
10. Field and Pool, or Wildcat Bagley (Penn.)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator Petrus Operating Company, Inc.
3. Address of Operator 12201 Merit Drive, Suite 900 Dallas, Texas 75251
4. Location of Well UNIT LETTER K 1874 FEET FROM THE South LINE AND 1874 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 11 S RANGE 33 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4256.0' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Spud well at 8:30 p.m. on 10-09-84. Drill 17-1/2" hole to 452'. Set 13-3/8" 54.5# K-55 casing at 450'. Cement by pump and plug method. Cemented with 450 sacks of Class C with 1/4# FLOCELE and 2% CaCl. Circ out 150 sx. Wait on cement for 20.5 hours. Test casing to 1000 psi for 30 minutes. No loss of pressure.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. L. Hardy C. L. Hardy

TITLE Drilling & Production Manager

DATE 10-15-84

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT 1 SUPERVISOR

APPROVED BY

TITLE

DATE OCT 19 1984

CONDITIONS OF APPROVAL, IF ANY: